## NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

## **MISCELLANEOUS NOTICES**

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

		Indicate Nature o	f Notice by C	hecking Bel	)W		
otice of Intention o Change Plans		Notice of Intenti Temporarily Abas			Notice of Intento Drill Deeper		
Notice of Intention O Plug Well	X	Notice of Intent	ION		Notice of Intento Set Liner	TION	
Notice of Intention to Squeeze		Notice of Intent	ion		Notice of Intento Shoot (Nitro		
Notice of Intention to Gun Perforate		Notice of Intent (Other)	ION		Notice of Inten (Other)	TION	
OIL CONSERVATION CONSANTA FE, NEW MEXICO		Eunice, N	ew Mexi	CØ	May 25	, 1956	
Gentlemen:				n.ı	- <b>h</b> ] - <i>M</i> +-+-		
Following is a Notice of	Intention to do	certain work as desc	ribed below a	t the	adto State	•	
Neville G. Penz	pany or Operator)		niapto	St.	Well No. 1	in ]	(Unit)
1/4	of Sec. 17	, T <b>10</b> \$	, <sub>R</sub> 27E	,NMPM.,	Wildcat		Peol
	(FOLLOW owing pro		in the Rui	les and r <b>abandon</b>	egulations) this well:		
tun 15 saek ceme 400'. Run 15 s	(FOLLOW cowing proportion of plug a cack cemen	ogram to plat 2124' (The plug in	ug and a D). She and out	abandon  oot and  of 5½	this well;  pull 5½" (csg. stub.	esg at ap	
tun 15 saek ceme 4001. Run 15 s	(FOLLOW cowing proportion of plug a cack cemen	ogram to plat 2124' (The plug in	ug and a D). She and out	abandon  oot and  of 5½	this well;  pull 5½" (csg. stub.	esg at ap	
tun 15 saek ceme 400'. Run 15 s	(FOLLOW cowing proportion of plug a cack cemen	ogram to plat 2124' (The plug in	ug and a D). She and out	abandon  oot and  of 5½	this well;  pull 5½" (csg. stub.	esg at ap	
tun 15 saek ceme 4001. Run 15 s	(FOLLOW cowing proportion of plug a cack cemen	ogram to plat 2124' (The plug in	ug and a D). She and out	abandon  oot and  of 5½	this well;  pull 5½" (csg. stub.	esg at ap	
Propose the follown 15 sack ceme 4001. Run 15 surface plug. E	(FOLLOW cowing proportion of plug a cack cemen	ogram to plat 2124' (The plug in	ug and a D). She and out	abandon  oot and  of 5½	this well;  pull 5½" (csg. stub.	esg at ap	
tun 15 sack ceme 400'. Run 15 s turface plug. E	(FOLLOW cowing proportion of plug a cack cemen	ogram to plat 2124' (The plug in 18' pipe man	ug and a D). She and out	es and a abandon oot and of 5½ noperly	this well;  pull 5½" (csg. stub.	Run 5	sack
tun 15 sack ceme 400'. Run 15 s surface plug. E	(FOLLOW OWING PROPERTY OF A PARTY	ogram to plat 2124' (The plug in 18' pipe man	ug and a D). She and out	es and a abandon oot and of 5½ noperly	this well:  pull 5½"  csg. stub.  inscribed.	Penrose	sack
tun 15 sack ceme 400'. Run 15 s surface plug. E	(FOLLOW Owing property of the plug of the	ogram to plat 2124' (The plug in 18' pipe man	ug and and out rker pro	abandon  oot and  of 5½  operly	this well:  pull 5½"  csg. stub.  inscribed.	Penrose T.H. E	sack

Address Bex 988

Eunice, New Mexico