

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

MAR 10 1971

C. C. C.

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>

5. State Oil & Gas Lease No.
State B-8385-1

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator TEXACO Inc. ✓ 3. Address of Operator P. O. BOX 728 - HOBBS, NEW MEXICO 88240 4. Location of Well UNIT LETTER N, 330 FEET FROM THE South LINE AND 1650 FEET FROM THE West LINE, SECTION 11 TOWNSHIP 11-S RANGE 27-E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 3704' GR	7. Unit Agreement Name - 8. Farm or Lease Name New Mexico 'AM' State 9. Well No. 2 10. Field and Pool, or Wildcat Coyote Queen 12. County Chaves
--	---

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The following work on subject well has been completed:

1. Ran 2" tubing to TD.
2. Displaced water with mud.
3. Spot 15 sx cement plug from 1039' to 890' over perforations 960' to 992' in 5-1/2" casing.
4. Pulled tubing.
5. Spot 10 sx cement plug at surface.
6. Cut off well head and install 4" Dry Hole Marker extending 4' above ground level. Clean location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Asst. District Superintendent DATE March 9, 1971

APPROVED BY [Signature] TITLE OIL AND GAS INSPECTOR DATE JUN 10 1971

CONDITIONS OF APPROVAL, IF ANY: