

N. M. O. C. C. COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
SUBMIT IN TRIPLICATE
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-067811A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Dale Federal

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

Jesse Springs
Linda San Andres11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

S 26, T 7 S, R 26 E

12. COUNTY OR PARISH

Chaves

13. STATE

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

AUG 18 1976

1. OIL ☐ GAS ☒ WELL ☐ OTHER ☐

2. NAME OF OPERATOR

H. E. Prince

3. ADDRESS OF OPERATOR

P. O. Box 129, Roswell, New Mexico,

O. C. C.
ARTESIA, OFFICE
882014. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface2310 feet from the N line and 1650 feet from the
W. line.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plug and abandon as follows:

Well depth 1475'

Run bottom plug with 15 sacks of cement from 1475' back to 1294.10'

Cut casing at 1014' and pull.

Run heavy mud from 1294.10 feet back to 155'.

Run 100 feet cement plug 50' in surface pipe and 50' in hole.

16 sacks in hole and 17 sack in surface pipe.

Run mud from 55' back to 10'

Run 10 feet cement plug and set marker.

Clean debris from site.

RECEIVED

AUG 16 1976

U. S. GEOLOGICAL SURVEY,
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

H. E. Prince

TITLE

Owner

DATE

8/10/76

(This space for Federal or State office use)

TITLE

DATE

APPROVED

AUG 17 1976

H. L. BEEKMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side