

NO. OF COPIES RECEIVED	2
DISTRIBUTION	
SANTA FE	1
FILE	1 ✓
U.S.G.S.	
LAND OFFICE	
OPERATOR	2

**RECEIVED**  
 NEW MEXICO OIL CONSERVATION COMMISSION  
**OCT 15 1974**  
**O. C. C.**  
 ARTESIA, OFFICE

Form C-103  
 Supersedes Old  
 C-102 and C-103  
 Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
 USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>H. T. PRINCE</b> ✓	8. Farm or Lease Name <b>PENDERGRASS</b>
3. Address of Operator <b>606 N. ATKINSON, ROSWELL, NEW MEXICO, 88201</b>	9. Well No. <b>3</b>
4. Location of Well UNIT LETTER <b>A</b> <b>330</b> FEET FROM THE <b>N.</b> LINE AND <b>330</b> FEET FROM THE <b>3</b> LINE, SECTION <b>5</b> TOWNSHIP <b>7S</b> RANGE <b>26E</b> NMPM.	10. Field and Pool, or Wildcat <b>LINDA SAN ANTOES</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3603 G R</b>	12. County <b>CHAVEZ</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**Plug and abandon as follows:**

**Well Depth 1026 ft.**

**Run 15 sacks of cement from 1026 back to 845.10'**

**Cut casing at 627.50'**

**Run mud from 845.10' back to 150'**

**Run 100' cement plug from 150' back to 50', 50' in and 50' out of surface pipe**

**Run mud from 50' back to 10'**

**Run cement from 10' back to surface and set marker**

**Clean debris from site.**

*4 1/2" csg. is circulated to surface.*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *H. T. Prince* TITLE **OWNER** DATE **10-10-74**

APPROVED BY *W. A. Gussert* TITLE **OIL AND GAS INSPECTOR** DATE **OCT 23 1974**

CONDITIONS OF APPROVAL, IF ANY:

Notify N.M.O.C.C. in sufficient time to witness