

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLI 3*
(Other instructions on
reverse side)

Copy to 51

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-067811A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Dale Federal

9. WELL NO.

7

10. FIELD AND POOL, OR WILDCAT

Jeslie Springs
Linda San Andres11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

S 26, T 7 S, R 26 E

12. COUNTY OR PARISH
Chaves13. STATE
N. M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different level.
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

1. OIL ☒ GAS ☐ OTHER ☐
WELL

2. NAME OF OPERATOR
H. E. Prince ✓

3. ADDRESS OF OPERATOR
P. O. Box 129, Roswell, New Mexico, 88201
O. C. C. ARTESIA OFFICE

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
1650' from the N. line and 990' from the w. line

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

SUBSEQUENT REPORT OF:

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

X

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plug and abandon as follows:

Well depth 1502'

Run bottom plug with 15 sacks of cement form 1502' back to 1381.55'

Cut casing at 546' and pull.

Run heavy mud from 1381.55' back to 200'

Run 100 feet cement plug 50' in hole and 50' in surface pipe.

17 sacks in surface pipe and 16 sacks in hole back 100'

Run mud back to 10'

Run 10 feet cement plug 4 sacks and set marker.

Clean debris from site.

RECEIVED

AUG 16 1976

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

76 & Prince

TITLE

Owner

DATE

8/10/76

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED

AUG 1976

R. L. BEEKHUN

ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side