

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLY
(Other instructions
verse side)U.
re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

L. C.-067811A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

H. E. Prince

AUG 14 1974

3. ADDRESS OF OPERATOR

606 N. Atkinson, Roswell, New Mexico 88201 D. C. C.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface2310 feet from the W. line and 1650 feet from
the N. line

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Dale Federal

9. WELL NO.

8

10. FIELD AND POOL, OR WILDCAT

Linda San Andres

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

S-26-T-7S-R26E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

12. COUNTY OR PARISH

Chaves

13. STATE

New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☒
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☐
☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plug and abandon as follows:

T. D. 1503 feet

Run bottom plug with 15 sacks of cement from 1503 feet back to ~~1473.75~~ feet.
Cut casing at 606 feet and pull.Run heavy mud from ~~1473.75~~ feet back to 150 feet.

Run 100 feet plug in surface pipe 50 feet in and 50 feet out.

16 sacks in hole and 17 sacks surface pipe back to 50 feet.

Run mud back to 10 feet and run 10 feet plug 4 sacks and set marker.

Clean debris from site.

RECEIVED

JUL 15 1974

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED H. E. PrinceTITLE ownerDATE 7/12/74

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OR APPROVAL, IF ANY

TITLE

DATE

APPROVED
AUG 13 1974
H. L. BEEKMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side