

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
K-2803

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

RECEIVED

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole	7. Unit Agreement Name
2. Name of Operator Donald G. Stevens	8. Farm or Lease Name Citgo State
3. Address of Operator P. O. Box 1797, Santa Fe, New Mexico 87501	9. Well No. 1
4. Location of Well UNIT LETTER P, 660 FEET FROM THE South LINE AND 660 FEET FROM THE East LINE, SECTION 36 TOWNSHIP 8 S RANGE 20 E NMPM.	10. Field and Pool, or Wildcat Twin Lakes, S.A.
15. Elevation (Show whether DF, RT, GR, etc.) 3983 GR	12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 9-29-73 W.O.C., Ran 2727' 4 1/2" 9.5# casing, cementing w/200 sax poz mix. W.O.C. 24 hours, pressured up to 1000# for 30 minutes, logging no pressure drawdown.
- 9-30-73 Perf 2623-33, 2642-4, 2652-60 w/2 spf, acidized w/4500 gallons 28% in 3 stages. Prep to swab.
- 10-2-73 Swabbed 15 hours 100 barrels acid and load water and oil. Swabbed dry.

Under verbal authority of Bill Gressett, N.M.O.C.C., propose to plug and abandon in the following manner:

1. Set 25 sack plug at T.D. across perfs 2623-60 up to 2520.
2. Set out 4 1/2 casing and set 35 sack plug 100' in and out of stub.
3. Set 35 sack plug in and out of 8-5/8 at 1005' to 905'.
4. Set 10 sack plug at surface and install regulation marker.
5. Will notify when ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Donald G. Stevens TITLE Pres. DATE 12-22-73

APPROVED BY W. A. Gressett TITLE OIL AND GAS INSPECTOR DATE JAN 31 1974

CONDITIONS OF APPROVAL, IF ANY: