

NO. OF COPIES RECEIVED	6
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	4

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator Charles B. Read		5. State Oil & Gas Lease No. K-6623
3. Address of Operator P. O. Box 2126 Roswell, New Mexico 88201		7. Unit Agreement Name
4. Location of Well UNIT LETTER F, 1650 FEET FROM THE North LINE AND 1650 FEET FROM THE West LINE, SECTION 36 TOWNSHIP 14S RANGE 27E N.M.P.M.		8. Farm or Lease Name Hondo-State
15. Elevation (Show whether DF, RT, GR, etc.) 3470.5 GL		9. Well No. 1
		10. Field and Pool, or Wildcat Buffalo Valley (undesig)
		12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/> OTHER <input type="checkbox"/>
	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>
	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

To set a 30 sx plug @ 7900' to 8000'
 To set a 30 sx plug @ 6700' to 6800'
 To set a 30 sx plug @ 5200' to 5300'
 To set a 30 sx plug @ 2800' to 2900'
 To cut and remove 8 5/8" csg.
 To set a 50 sx plug in top of casing stub
 To set a 50 sx plug @ 250' to 350'
 To set a 50 sx plug @ 0' to 10'.

RECEIVED

FEB 20 1969

O. C. C.
ARTEZIA, OFFICE

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. A. Gussett TITLE Agent DATE 1-9-69

APPROVED BY W. A. Gussett TITLE Oil and Gas Inspector DATE MAR 6 1969

CONDITIONS OF APPROVAL, IF ANY:

30 sack Plug @ base 8848"