

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	

RECEIVED
 NEW MEXICO OIL CONSERVATION COMMISSION
 APR 10 1970
 C.O.C.
 ALBUQUERQUE, OFFICE

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
K-175	
7. Unit Agreement Name	
8. Farm or Lease Name	
Bell State	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
Wildcat	
12. County	
Chaves	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>
2. Name of Operator
Hanson Oil Company
3. Address of Operator
P. O. Box 1515, Roswell, New Mexico, 88201
4. Location of Well
UNIT LETTER <u>P</u> , <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>2</u> TOWNSHIP <u>14-S</u> RANGE <u>28-E</u> N.M.P.M.
15. Elevation (Show whether DF, RT, GR, etc.)
3615' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-20-70 Ran 8-5/8" @ 334' w/175 sx. circ. to surf.

2-21-70 Bailed hole dry and drilled out plug. Tested 1 hr. with no water.

3-03-70 ~~20"~~ FSW @ 1260-70
Ran & mudded 7" @ 1285'.

3-09-70 T.D. 1530'. HFW @ 1500'. Pulled 7" and began straight reaming.

3-15-70 Reamed 8" hole to 1530'. Ran 7" @ 1530' w/100 sx.

3-16-70 Bailed hole dry and drilled out plug. Tested 1 hr. with no water.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Harry F. Schmitt</u>	TITLE <u>Exec. Vice-President</u>	DATE <u>3-17-70</u>
APPROVED BY <u>W.A. Gressett</u>	TITLE <u>OIL AND GAS INSPECTOR</u>	DATE <u>APR 10 1970</u>

CONDITIONS OF APPROVAL, IF ANY: