Now the same of th

Copy J.

DISTRIBUTION SANTA FE FILE U.S.G.S. LAND OFFICE	RECEIVED	Form C-103
SANTA FE FILE U.S.G.S.	RECEIVED	
FILE U.S.G.S.		Supersedes Old C-102 and C-103
U.S.G.S.	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
· · · · · · · · · · · · · · · · · · ·	JUL 2.7.19 7 2	
LAND OFFICE	JOE 5 / 18/2	5a. Indicate Type of Lease
		State Fee
OPERATOR	C.C.C.	5. State Oil & Gas Lease No.
	ARTESIA, OFFICE	NM 0390091
SUNDRY (DO NOT USE THIS FORM FOR PROPUSE "APPLICATION	Y NOTICES AND REPORTS ON WELLS POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. ON FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)	
l. OIL GAS WELL WELL	OTHER- TYPE	7. Unit Agreement Name
2. Name of Operator SHENANDOAH CIL CORPCRATION		8, Farm or Lease Name Lead & St. Vens, INC Fod val
3. Address of Operator		9. Well No.
702 V-J TOWER	Bldg, Midland, Toxas 79701	10, Field and Pool, or Wildcat
•	980 FEET FROM THE NORTH LINE AND 1980 F	A A A A A A A A A A A A A A A A A A A
	N 20 TOWNSHIP 6-S RANGE 27-E	
		_ NMPM.
	15. Elevation (Show whether DF, RT, GR, etc.) 3952.6 GF	12. County Chav s
	Appropriate Box To Indicate Nature of Notice, Report	
NOTICE OF IN	TENTION TO: SUBSE	EQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
	OTHER	
OTHER		
depth of 6600	g d and abandoned as a fey hole aft . Plugging operations were perfor lass H cmt. plug from 6300'-6400'	The state of the s
Spot 35 sm. C. Spot 35 sm. C. Spot 10 sm. C. Spot 0 sm. C. Complet 6 6:3 cmt.plug in to	lass H cmt. plug from 5700'-5800' lass H cmt. plug from 4400'-4500' lass H cmt. plug from 2600'-2750' lass H cmt. plug f om 1300'-1450' lo PM, 9-13-71. Take up BOP, clean cop of 8-5/8" surfac cog. Deleas de	rig 10:00 PM, 9-13-71.
Spot 35 sm. C. Spot 35 sm. C. Spot 10 sm. C. Spot 10 sm. C. Complet 6 6:3 cmt.plug in to Regulation wi	lass H cmt. plug from 5700'-5800' lass H cmt. plug from 4400'-4500' lass H cmt. plug from 2600'-2750' lass H cmt. plug f om 1300'-1450' 0 PM, 9-13-71. Take up BOP, clean c	rig 10:00 PM, 9-13-71.
Spot 35 sm. C. Spot 35 sm. C. Spot 10 sm. C. Spot 0 sm. C. Complet 6 13 cmt.plug in to Regulation wi	lass H cmt. plug from 5700'-5800' lass H cmt. plug from 4400'-4500' lass H cmt. plug from 2600'-2750' lass H cmt. plug f om 1300'-1450' lo PM, 9-13-71. Take up BOP, clean cop of 8-5/8" surface csg. meleased ll be installed and U.S.G.S. will be	rig 10:00 PM, 9-13-71.