Form 9-331

16.

## L .. TED STATES

SUBN	11T	IN	TR	<b>ICAT</b>	$\mathbf{F}$
(Othe	r i	nstr	uctions	on	re
verse	side	• )			

Copy 651

	Form approved,					
	Budget	Burea	n N	0. 4	2 - R	1424
LEASE	DESIGN	ATION	AÑD	SER	TAL	NO.

Mi	DEPARTMENT OF THE INTERIOR (Other Instructions on re- GEOLOGICAL SURVEY	5. LEASE DESIGNATION A  N.M. 0154	nd serial no. 766
	SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE	OR TRIBE NAME
l.	OIL X GAS WELL OTHER	7. UNIT AGREEMENT NAM	
2.	MCCLELLAN OIL CORPORATION OCT 1 1 1972	8. FARM OR LEASE NAME BAR J FED	
3.	BOX 848 ROSWELL, N.MEX. 88201 .C.C.	9. WELL NO.	
4.	LOCATION OF WELL (Report location clearly and in accordance with any attestantice	10. FIELD AND POOL, OR	
	660 FNL & 1980 FWL	11. SEC., T., R., M., OR BI SURVEY OR AREA 15-6S-27E	JK, AND
14.	PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH	13. STATE
	4090 GR.	CHAVES	N.MEX.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF		PULL OR ALTER CASING		WATER SHUT-OFF	REPAIRING WELL	_
FRACTURE TREAT		MULTIPLE COMPLETE		FRACTURE TREATMENT	ALTERING CASING	
SHOOT OR ACIDIZE		ABANDON*		SHOOTING OR ACIDIZING	ABANDON MENT*	
REPAIR WELL		CHANGE PLANS		(Other)		
(Other) RECOMP	LETE		X	(Note: Report results of mult Completion or Recompletion Re	iple completion on Well eport and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) •

THE PRODUCING ZONE FROM 6501-6511 HAS DECREASED TO 6-8 BBLS PER DAY AND IS NOT ECONOMICAL TO PRODUCE. PLAN TO SET CAST IRON BRIDGE PLUG AT 6400, PERFORATE ZONE FROM 6339-6349 AND ACIDIZE WITH 250 GAL. OF 15% MUD ACID AND SWAB TO TEST. IF ZONE IS PRODUCTIVE, COMPLETE IN THIS ZONE. IF NOT PRODUCTIVE, SET CAST IRON BRIDGE PLUG AT 6000.

PERFORATE IN CISCO ZONE FROM 5938-5948, ACIDIZE WITH 250 GAL. OF 15% MUD ACID AND SWAB TO TEST.

001101972

18. I hereby certify that the for going is true and correct	TITLE PRODUCTION	SUPERINTENDENT	ост. 6,1972
(This space for Federal or State office use)			
APPROVED BY CONDITIONS OF APPROVIL, IF ANY:	TITLE	DAT	<b>E</b>

\*See Instructions on Reverse Side