NO. OF COPIES RECEIVED		
DISTRIBUTION		Form C-103
DISTRIBUTION		Supersedes Old C-102 and C-103
SANTA FE NEW A	インでの MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE	4.0 M/A	
U.S.G.S. NOV 6	1972	5a. Indicate Type of Lease
LAND OFFICE		State Y Fee
OPERATOR C	<b>,</b> 1	5. State Oil & Gas Lease No.
D. C.		T3344
SLINDRY NOTICES AN	D PEDOTS ON WELLS	111111111111111111111111111111111111111
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR USE "APPLICATION FOR PERMIT _"	D REPORTS ON WELLS TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. (FORM C-101) FOR SUCH PROPOSALS.)	
1.	TOTAL COLOTA FROPOSALS.)	7. Unit Agreement Name
OIL GAS WELL OTHER.		7. Our Agreement Name
2. Name of Operator		
Secan Oil Company Incorporated		8. Farm or Lease Name
Secan Oil Company, Incorporated  3. Address of Operator		State
		9. Well No.
Post Office Box 1246, Natchez, Mississippi 39120		1
Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER G , 1980 FEET FRO	OM THE North LINE AND 1980 FEET FR	WC - Devonian
<del>-</del>	PEET FR	
THE East LINE SECTION 26	TOWNSHIP 11 South ANGE 27 East NM	
EIRE, SECTION	NMI	.w. (///////////////////////////////////
15. Elev	ation (Show whether DF, RT, GR, etc.)	12. County
	• •	Millilli
	DF 3771'	Chaves
Check Appropriate Box	x To Indicate Nature of Notice, Report or (	Other Data
NOTICE OF INTENTION TO:	SUBSEQUE	NT REPORT OF:
<del></del>		
PERFORM REMEDIAL WORK PLU	IG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING CHA	NGE PLANS CASING TEST AND CEMENT JOB	
	OTHERperforate and	l test x
OTHER		X.
<ol> <li>Describe Proposed or Completed Operations (Clearly stamork) SEE RULE 1103</li> </ol>	ate all pertinent details, and give pertinent dates, includi	ng estimated date of starting any proposed
work) 322 NO22 1103.		ng estimated date of starting any proposed
1. Set 2-3/8" EUE N80 tubing at 67	794' on R-4 Packer - 10-7-72	
<ol> <li>Set 2-3/8" EUE N80 tubing at 67</li> <li>Swabbed down and perforated 687</li> </ol>	794' on R-4 Packer - 10-7-72 73'-81' with 1-11/16" Welex tubing	gun 4SPF - 10-8-72
<ol> <li>Set 2-3/8" EUE N80 tubing at 67</li> <li>Swabbed down and perforated 687</li> <li>Swabbed 40° gravity oil and gas</li> </ol>	794' on R-4 Packer - 10-7-72 73'-81' with 1-11/16" Welex tubing 3 natural - 10-8-72 thru 10-10-72	gun 4SPF - 10-8-72
<ol> <li>Set 2-3/8" EUE N80 tubing at 67</li> <li>Swabbed down and perforated 687</li> <li>Swabbed 40° gravity oil and gas</li> </ol>	794' on R-4 Packer - 10-7-72 73'-81' with 1-11/16" Welex tubing 3 natural - 10-8-72 thru 10-10-72	gun 4SPF - 10-8-72
<ol> <li>Set 2-3/8" EUE N80 tubing at 67</li> <li>Swabbed down and perforated 687</li> <li>Swabbed 40° gravity oil and gas</li> <li>Acidized with 500 gallons Halli</li> </ol>	794' on R-4 Packer - 10-7-72 73'-81' with 1-11/16" Welex tubing 3 natural - 10-8-72 thru 10-10-72 1burton MCA, then swabbed 100% SW	gun 4SPF - 10-8-72
<ol> <li>Set 2-3/8" EUE N80 tubing at 67</li> <li>Swabbed down and perforated 687</li> <li>Swabbed 40° gravity oil and gas</li> <li>Acidized with 500 gallons Halli</li> <li>Set Welex cast iron bridge plug</li> </ol>	794' on R-4 Packer - 10-7-72 73'-81' with 1-11/16" Welex tubing a natural - 10-8-72 thru 10-10-72 iburton MCA, then swabbed 100% SW at 6860' - 10-15-72	gun 4SPF - 10-8-72
1. Set 2-3/8" EUE N80 tubing at 67 2. Swabbed down and perforated 687 3. Swabbed 40° gravity oil and gas 4. Acidized with 500 gallons Halli 5. Set Welex cast iron bridge plug 6. Perforated 6218'-28' with Welex	794' on R-4 Packer - 10-7-72 73'-81' with 1-11/16" Welex tubing s natural - 10-8-72 thru 10-10-72 iburton MCA, then swabbed 100% SW g at 6860' - 10-15-72 s casing gun 4SPF - 10-15-72	gun 4SPF - 10-8-72
1. Set 2-3/8" EUE N80 tubing at 67 2. Swabbed down and perforated 687 3. Swabbed 40° gravity oil and gas 4. Acidized with 500 gallons Halli 5. Set Welex cast iron bridge plug 6. Perforated 6218'-28' with Welex 7. Acidized with 1000 gallons HEL	794' on R-4 Packer - 10-7-72 73'-81' with 1-11/16" Welex tubing 8 natural - 10-8-72 thru 10-10-72 1burton MCA, then swabbed 100% SW 9 at 6860' - 10-15-72 1 casing gun 4SPF - 10-15-72 1 by Halliburton - 10-15-72	gun 4SPF - 10-8-72
1. Set 2-3/8" EUE N80 tubing at 67 2. Swabbed down and perforated 687 3. Swabbed 40° gravity oil and gas 4. Acidized with 500 gallons Halli 5. Set Welex cast iron bridge plug 6. Perforated 6218'-28' with Welex 7. Acidized with 1000 gallons HEL 8. Swabbed down with no entry from	794' on R-4 Packer - 10-7-72 73'-81' with 1-11/16" Welex tubing 8 natural - 10-8-72 thru 10-10-72 1burton MCA, then swabbed 100% SW 9 at 6860' - 10-15-72 1 casing gun 4SPF - 10-15-72 1 by Halliburton - 10-15-72	gun 4SPF - 10-8-72
1. Set 2-3/8" EUE N80 tubing at 67 2. Swabbed down and perforated 687 3. Swabbed 40° gravity oil and gas 4. Acidized with 500 gallons Halli 5. Set Welex cast iron bridge plug 6. Perforated 6218'-28' with Welex 7. Acidized with 1000 gallons HEL	794' on R-4 Packer - 10-7-72 73'-81' with 1-11/16" Welex tubing 8 natural - 10-8-72 thru 10-10-72 1burton MCA, then swabbed 100% SW 9 at 6860' - 10-15-72 1 casing gun 4SPF - 10-15-72 1 by Halliburton - 10-15-72	gun 4SPF - 10-8-72
1. Set 2-3/8" EUE N80 tubing at 67 2. Swabbed down and perforated 687 3. Swabbed 40° gravity oil and gas 4. Acidized with 500 gallons Halli 5. Set Welex cast iron bridge plug 6. Perforated 6218'-28' with Welex 7. Acidized with 1000 gallons HEL 8. Swabbed down with no entry from	794' on R-4 Packer - 10-7-72 73'-81' with 1-11/16" Welex tubing 8 natural - 10-8-72 thru 10-10-72 1burton MCA, then swabbed 100% SW 9 at 6860' - 10-15-72 1 casing gun 4SPF - 10-15-72 1 by Halliburton - 10-15-72	gun 4SPF - 10-8-72
1. Set 2-3/8" EUE N80 tubing at 67 2. Swabbed down and perforated 687 3. Swabbed 40° gravity oil and gas 4. Acidized with 500 gallons Halli 5. Set Welex cast iron bridge plug 6. Perforated 6218'-28' with Welex 7. Acidized with 1000 gallons HEL 8. Swabbed down with no entry from	794' on R-4 Packer - 10-7-72 73'-81' with 1-11/16" Welex tubing 8 natural - 10-8-72 thru 10-10-72 1burton MCA, then swabbed 100% SW 9 at 6860' - 10-15-72 1 casing gun 4SPF - 10-15-72 1 by Halliburton - 10-15-72	gun 4SPF - 10-8-72
1. Set 2-3/8" EUE N80 tubing at 67 2. Swabbed down and perforated 687 3. Swabbed 40° gravity oil and gas 4. Acidized with 500 gallons Halli 5. Set Welex cast iron bridge plug 6. Perforated 6218'-28' with Welex 7. Acidized with 1000 gallons HEL 8. Swabbed down with no entry from	794' on R-4 Packer - 10-7-72 73'-81' with 1-11/16" Welex tubing 8 natural - 10-8-72 thru 10-10-72 1burton MCA, then swabbed 100% SW 9 at 6860' - 10-15-72 1 casing gun 4SPF - 10-15-72 1 by Halliburton - 10-15-72	gun 4SPF - 10-8-72
1. Set 2-3/8" EUE N80 tubing at 67 2. Swabbed down and perforated 687 3. Swabbed 40° gravity oil and gas 4. Acidized with 500 gallons Halli 5. Set Welex cast iron bridge plug 6. Perforated 6218'-28' with Welex 7. Acidized with 1000 gallons HEL 8. Swabbed down with no entry from	794' on R-4 Packer - 10-7-72 73'-81' with 1-11/16" Welex tubing 8 natural - 10-8-72 thru 10-10-72 1burton MCA, then swabbed 100% SW 9 at 6860' - 10-15-72 1 casing gun 4SPF - 10-15-72 1 by Halliburton - 10-15-72	gun 4SPF - 10-8-72
1. Set 2-3/8" EUE N80 tubing at 67 2. Swabbed down and perforated 687 3. Swabbed 40° gravity oil and gas 4. Acidized with 500 gallons Halli 5. Set Welex cast iron bridge plug 6. Perforated 6218'-28' with Welex 7. Acidized with 1000 gallons HEL 8. Swabbed down with no entry from	794' on R-4 Packer - 10-7-72 73'-81' with 1-11/16" Welex tubing 8 natural - 10-8-72 thru 10-10-72 1burton MCA, then swabbed 100% SW 9 at 6860' - 10-15-72 1 casing gun 4SPF - 10-15-72 1 by Halliburton - 10-15-72	gun 4SPF - 10-8-72
1. Set 2-3/8" EUE N80 tubing at 67 2. Swabbed down and perforated 687 3. Swabbed 40° gravity oil and gas 4. Acidized with 500 gallons Halli 5. Set Welex cast iron bridge plug 6. Perforated 6218'-28' with Welex 7. Acidized with 1000 gallons HEL 8. Swabbed down with no entry from	794' on R-4 Packer - 10-7-72 73'-81' with 1-11/16" Welex tubing 8 natural - 10-8-72 thru 10-10-72 1burton MCA, then swabbed 100% SW 9 at 6860' - 10-15-72 1 casing gun 4SPF - 10-15-72 1 by Halliburton - 10-15-72	gun 4SPF - 10-8-72
1. Set 2-3/8" EUE N80 tubing at 67 2. Swabbed down and perforated 687 3. Swabbed 40° gravity oil and gas 4. Acidized with 500 gallons Halli 5. Set Welex cast iron bridge plug 6. Perforated 6218'-28' with Welex 7. Acidized with 1000 gallons HEL 8. Swabbed down with no entry from	794' on R-4 Packer - 10-7-72 73'-81' with 1-11/16" Welex tubing 8 natural - 10-8-72 thru 10-10-72 1burton MCA, then swabbed 100% SW 9 at 6860' - 10-15-72 1 casing gun 4SPF - 10-15-72 1 by Halliburton - 10-15-72	gun 4SPF - 10-8-72
1. Set 2-3/8" EUE N80 tubing at 67 2. Swabbed down and perforated 687 3. Swabbed 40° gravity oil and gas 4. Acidized with 500 gallons Halli 5. Set Welex cast iron bridge plug 6. Perforated 6218'-28' with Welex 7. Acidized with 1000 gallons HEL 8. Swabbed down with no entry from	794' on R-4 Packer - 10-7-72 73'-81' with 1-11/16" Welex tubing 8 natural - 10-8-72 thru 10-10-72 1burton MCA, then swabbed 100% SW 9 at 6860' - 10-15-72 1 casing gun 4SPF - 10-15-72 1 by Halliburton - 10-15-72	gun 4SPF - 10-8-72
1. Set 2-3/8" EUE N80 tubing at 67 2. Swabbed down and perforated 687 3. Swabbed 40° gravity oil and gas 4. Acidized with 500 gallons Halli 5. Set Welex cast iron bridge plug 6. Perforated 6218'-28' with Welex 7. Acidized with 1000 gallons HEL 8. Swabbed down with no entry from	794' on R-4 Packer - 10-7-72 73'-81' with 1-11/16" Welex tubing 8 natural - 10-8-72 thru 10-10-72 1burton MCA, then swabbed 100% SW 9 at 6860' - 10-15-72 1 casing gun 4SPF - 10-15-72 1 by Halliburton - 10-15-72	gun 4SPF - 10-8-72
<ol> <li>Set 2-3/8" EUE N80 tubing at 67</li> <li>Swabbed down and perforated 687</li> <li>Swabbed 40° gravity oil and gas</li> <li>Acidized with 500 gallons Halli</li> <li>Set Welex cast iron bridge plug</li> <li>Perforated 6218'-28' with Welex</li> <li>Acidized with 1000 gallons HEL</li> <li>Swabbed down with no entry from</li> </ol>	794' on R-4 Packer - 10-7-72 73'-81' with 1-11/16" Welex tubing 8 natural - 10-8-72 thru 10-10-72 1burton MCA, then swabbed 100% SW 9 at 6860' - 10-15-72 1 casing gun 4SPF - 10-15-72 1 by Halliburton - 10-15-72	gun 4SPF - 10-8-72
1. Set 2-3/8" EUE N80 tubing at 67 2. Swabbed down and perforated 687 3. Swabbed 40° gravity oil and gas 4. Acidized with 500 gallons Halli 5. Set Welex cast iron bridge plug 6. Perforated 6218'-28' with Welex 7. Acidized with 1000 gallons HEL 8. Swabbed down with no entry from 9. Shut down - 10-16-72	794' on R-4 Packer - 10-7-72 73'-81' with 1-11/16" Welex tubing a natural - 10-8-72 thru 10-10-72 iburton MCA, then swabbed 100% SW at 6860' - 10-15-72 a casing gun 4SPF - 10-15-72 by Halliburton - 10-15-72 a formation - 10-15-72	gun 4SPF - 10-8-72
1. Set 2-3/8" EUE N80 tubing at 67 2. Swabbed down and perforated 687 3. Swabbed 40° gravity oil and gas 4. Acidized with 500 gallons Halli 5. Set Welex cast iron bridge plug 6. Perforated 6218'-28' with Welex 7. Acidized with 1000 gallons HEL 8. Swabbed down with no entry from 9. Shut down - 10-16-72	794' on R-4 Packer - 10-7-72 73'-81' with 1-11/16" Welex tubing a natural - 10-8-72 thru 10-10-72 iburton MCA, then swabbed 100% SW at 6860' - 10-15-72 a casing gun 4SPF - 10-15-72 by Halliburton - 10-15-72 a formation - 10-15-72	gun 4SPF - 10-8-72
1. Set 2-3/8" EUE N80 tubing at 67 2. Swabbed down and perforated 687 3. Swabbed 40° gravity oil and gas 4. Acidized with 500 gallons Halli 5. Set Welex cast iron bridge plug 6. Perforated 6218'-28' with Welex 7. Acidized with 1000 gallons HEL 8. Swabbed down with no entry from 9. Shut down - 10-16-72	794' on R-4 Packer - 10-7-72 73'-81' with 1-11/16" Welex tubing a natural - 10-8-72 thru 10-10-72 iburton MCA, then swabbed 100% SW at 6860' - 10-15-72 a casing gun 4SPF - 10-15-72 by Halliburton - 10-15-72 a formation - 10-15-72	gun 4SPF - 10-8-72
1. Set 2-3/8" EUE N80 tubing at 67 2. Swabbed down and perforated 687 3. Swabbed 40° gravity oil and gas 4. Acidized with 500 gallons Halli 5. Set Welex cast iron bridge plug 6. Perforated 6218'-28' with Welex 7. Acidized with 1000 gallons HEL 8. Swabbed down with no entry from 9. Shut down - 10-16-72	794' on R-4 Packer - 10-7-72 73'-81' with 1-11/16" Welex tubing a natural - 10-8-72 thru 10-10-72 iburton MCA, then swabbed 100% SW at 6860' - 10-15-72 casing gun 4SPF - 10-15-72 by Halliburton - 10-15-72 in formation - 10-15-72	gun 4SPF - 10-8-72
1. Set 2-3/8" EUE N80 tubing at 67 2. Swabbed down and perforated 687 3. Swabbed 40° gravity oil and gas 4. Acidized with 500 gallons Halli 5. Set Welex cast iron bridge plug 6. Perforated 6218'-28' with Welex 7. Acidized with 1000 gallons HEL 8. Swabbed down with no entry from 9. Shut down - 10-16-72	794' on R-4 Packer - 10-7-72 73'-81' with 1-11/16" Welex tubing a natural - 10-8-72 thru 10-10-72 iburton MCA, then swabbed 100% SW at 6860' - 10-15-72 a casing gun 4SPF - 10-15-72 by Halliburton - 10-15-72 a formation - 10-15-72	gun 4SPF - 10-8-72
1. Set 2-3/8" EUE N80 tubing at 67 2. Swabbed down and perforated 687 3. Swabbed 40° gravity oil and gas 4. Acidized with 500 gallons Halli 5. Set Welex cast iron bridge plug 6. Perforated 6218'-28' with Welex 7. Acidized with 1000 gallons HEL 8. Swabbed down with no entry from 9. Shut down - 10-16-72	794' on R-4 Packer - 10-7-72 73'-81' with 1-11/16" Welex tubing a natural - 10-8-72 thru 10-10-72 iburton MCA, then swabbed 100% SW at 6860' - 10-15-72 casing gun 4SPF - 10-15-72 by Halliburton - 10-15-72 in formation - 10-15-72	gun 4SPF - 10-8-72
1. Set 2-3/8" EUE N80 tubing at 67 2. Swabbed down and perforated 687 3. Swabbed 40° gravity oil and gas 4. Acidized with 500 gallons Halli 5. Set Welex cast iron bridge plug 6. Perforated 6218'-28' with Welex 7. Acidized with 1000 gallons HEL 8. Swabbed down with no entry from	794' on R-4 Packer - 10-7-72 73'-81' with 1-11/16" Welex tubing a natural - 10-8-72 thru 10-10-72 iburton MCA, then swabbed 100% SW at 6860' - 10-15-72 casing gun 4SPF - 10-15-72 by Halliburton - 10-15-72 in formation - 10-15-72	gun 4SPF - 10-8-72

CONDITIONS OF APPROVAL, IF ANY: