

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

AUG 17 1976

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

O. C. C.

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No. -----
7. Unit Agreement Name -----
8. Farm or Lease Name White
9. Well No. 1
10. Field and Pool, or Wildcat <i>Face Track Dev., Undesignated</i>
12. County Chaves

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole
2. Name of Operator Hanagan Petroleum Corporation
3. Address of Operator P.O. Box 1737, Roswell, New Mexico 88201
4. Location of Well UNIT LETTER <u>K</u> , <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>2310</u> FEET FROM THE <u>West</u> LINE, SECTION <u>13</u> TOWNSHIP <u>10S</u> RANGE <u>27E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3800 (KB)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/24/76: Plugged and abandoned as follows:(T.D. 6995 im.& cht.) Set 100' plugs with 25 sx. each @ 6850'-6950', 5800'-5900', 4250'-4350', 2750'-2850' and a 30 sx. plug in & out of casing @1550'-1650' (casing set @1610'). Heavy drilling mud in place between plugs. Set 10 sx. surface plug with appropriate dry hole marker to be installed. No casing pulled.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Stuart D. Hanson TITLE AGENT DATE 8-16-76

APPROVED BY [Signature] TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: