	Form C-103
Office District I Energy, Minerals and Natural I	Resources Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II 811 South First Artesia NM 88210 OIL CONSERVATION DI	VISION 30005-61007
811 South First, Artesia, NM 88210 OIL CONSERVATION DI District III 2040 South Pacheco	1 1 Indicate Type of Lease
1000 Die Droges Dd. Agtee NM 97410	STATE IXI FEE
District IV Santa Fe, NM 8/503	6. State Oil & Gas Lease No.
2040 South Pacheco, Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG B	7. Lease Name or Unit Agreement Name:
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SU	ICIT
PROPOSALS.)	Twin Lakes San Andres Unit
1. Type of Well:	
Oil Well Gas Well Other Injection	
2. Name of Operator	7. Well No.
Concho Oil & Gas Corp.	68
3. Address of Operator	8. Pool name or Wildcat
110 W. Louisiana Ste 410; Midland, Tx 79701	Twin Lakes; San Andres (Assoc)
4. Well Location	,
Unit Letter E: 1650 Feet from theNorth line as	nd 330 feet from the West line
Olite Edited	
Section 6 Township 9S Rang	e 29E NMPM Chaves County
10. Elevation (Show whether DR, R.	
3995 GR	
11. Check Appropriate Box to Indicate Natur	e of Notice Report or Other Data
• • • • • • • • • • • • • • • • • • • •	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK  PLUG AND ABANDON  RE	MEDIAL WORK ALTERING CASING
	NAME OF THE OFFICE OFFICE OF THE OFFICE OF THE OFFICE OF THE OFFICE OFFICE OF THE OFFICE OF THE OFFICE OF THE OFFI
TEMPORARILY ABANDON	DMMENCE DRILLING OPNS. PLUG AND
PULL OR ALTER CASING	ASING TEST AND
	ASING TEST AND
	MENTIOR /
	EMENT JOB
COMPLETION	EMENT JOB  THER:: Run MIT/Acidize well/Return to Inj
OTHER COMPLETION CE	THER:: Run MIT/Acidize well/Return to Inj
OTHER  COMPLETION  CE  OT  12. Describe proposed or completed operations. (Clearly state all pertine	THER:: Run MIT/Acidize well/Return to Inj nt details, and give pertinent dates, including estimated date
OTHER  COMPLETION  CE  OTHER  Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Completed operations.	THER:: Run MIT/Acidize well/Return to Inj nt details, and give pertinent dates, including estimated date
OTHER  COMPLETION  CE  OTHER  Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Comport recompilation.	THER:: Run MIT/Acidize well/Return to Inj nt details, and give pertinent dates, including estimated date
OTHER  COMPLETION  CE  OTHER  Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Compor recompilation.  O5-22-01  Release pkr & tag bottom @ 2709'. POOH w/ tbg.	THER:: Run MIT/Acidize well/Return to Inj nt details, and give pertinent dates, including estimated date pletions: Attach wellbore diagram of proposed completion
OTHER  COMPLETION  CE  OTHER  Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Compor recompilation.  O5-22-01  Release pkr & tag bottom @ 2709'. POOH w/ tbg.  O5-23-01  TIH w/ 3-7/8" bit & bailer. CO to 2746', POOH w/ bailer.	THER:: Run MIT/Acidize well/Return to Inj nt details, and give pertinent dates, including estimated date pletions: Attach wellbore diagram of proposed completion er & bit.
OTHER  COMPLETION  CE  OTHER  Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Compor recompilation.  O5-22-01  Release pkr & tag bottom @ 2709'. POOH w/ tbg.  O5-23-01  TIH w/ 3-7/8" bit & bailer. CO to 2746', POOH w/ baile 05-24-01  Test tbg in hole. Set pkr @ 2601' & tested annulus to 32	THER:: Run MIT/Acidize well/Return to Inj nt details, and give pertinent dates, including estimated date pletions: Attach wellbore diagram of proposed completion er & bit. 20#. (chart attached) RD.
OTHER  COMPLETION  CE  OTHER  Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Compor recompilation.  O5-22-01  Release pkr & tag bottom @ 2709'. POOH w/ tbg.  O5-23-01  TIH w/ 3-7/8" bit & bailer. CO to 2746', POOH w/ bailed of the state of the start of the sta	THER:: Run MIT/Acidize well/Return to Inj nt details, and give pertinent dates, including estimated date pletions: Attach wellbore diagram of proposed completion er & bit. 20#. (chart attached) RD.
OTHER  COMPLETION  CE  OTHER  Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Compor recompilation.  O5-22-01  Release pkr & tag bottom @ 2709'. POOH w/ tbg.  O5-23-01  TIH w/ 3-7/8" bit & bailer. CO to 2746', POOH w/ bailed of the state of the start of the sta	THER:: Run MIT/Acidize well/Return to Inj nt details, and give pertinent dates, including estimated date pletions: Attach wellbore diagram of proposed completion er & bit. 20#. (chart attached) RD.
OTHER  COMPLETION  CE  OTHER  Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Compor recompilation.  O5-22-01  Release pkr & tag bottom @ 2709'. POOH w/ tbg.  O5-23-01  TIH w/ 3-7/8" bit & bailer. CO to 2746', POOH w/ baile of the state of the stat	THER:: Run MIT/Acidize well/Return to Inj nt details, and give pertinent dates, including estimated date pletions: Attach wellbore diagram of proposed completion er & bit. 20#. (chart attached) RD.
OTHER  COMPLETION  CE  OTHER  Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Compor recompilation.  O5-22-01  Release pkr & tag bottom @ 2709'. POOH w/ tbg.  O5-23-01  TIH w/ 3-7/8" bit & bailer. CO to 2746', POOH w/ baile of the start of the star	THER:: Run MIT/Acidize well/Return to Inj nt details, and give pertinent dates, including estimated date pletions: Attach wellbore diagram of proposed completion er & bit. 20#. (chart attached) RD.
OTHER  COMPLETION  CE  OTHER  Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Compor recompilation.  O5-22-01  Release pkr & tag bottom @ 2709'. POOH w/ tbg.  O5-23-01  TIH w/ 3-7/8" bit & bailer. CO to 2746', POOH w/ baile of the state of the stat	THER:: Run MIT/Acidize well/Return to Inj nt details, and give pertinent dates, including estimated date pletions: Attach wellbore diagram of proposed completion er & bit. 20#. (chart attached) RD.
OTHER  COMPLETION  CE  OTHER  Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Compor recompilation.  O5-22-01  Release pkr & tag bottom @ 2709'. POOH w/ tbg.  O5-23-01  TIH w/ 3-7/8" bit & bailer. CO to 2746', POOH w/ baile of the start of the star	THER:: Run MIT/Acidize well/Return to Inj nt details, and give pertinent dates, including estimated date pletions: Attach wellbore diagram of proposed completion er & bit. 20#. (chart attached) RD.
OTHER  COMPLETION  CE  OTHER  Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Compor recompilation.  O5-22-01  Release pkr & tag bottom @ 2709'. POOH w/ tbg.  O5-23-01  TIH w/ 3-7/8" bit & bailer. CO to 2746', POOH w/ baile of the start of the star	THER:: Run MIT/Acidize well/Return to Inj nt details, and give pertinent dates, including estimated date pletions: Attach wellbore diagram of proposed completion er & bit. 20#. (chart attached) RD.
OTHER  COMPLETION  CE  OTHER  Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Compor recompilation.  O5-22-01  Release pkr & tag bottom @ 2709'. POOH w/ tbg.  O5-23-01  TIH w/ 3-7/8" bit & bailer. CO to 2746', POOH w/ baile of the start of the star	THER:: Run MIT/Acidize well/Return to Inj nt details, and give pertinent dates, including estimated date pletions: Attach wellbore diagram of proposed completion er & bit. 20#. (chart attached) RD.
OTHER  COMPLETION  CE  OTHER  Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Compor recompilation.  O5-22-01  Release pkr & tag bottom @ 2709'. POOH w/ tbg.  O5-23-01  TIH w/ 3-7/8" bit & bailer. CO to 2746', POOH w/ baile of the start of the star	THER:: Run MIT/Acidize well/Return to Inj nt details, and give pertinent dates, including estimated date pletions: Attach wellbore diagram of proposed completion er & bit. 20#. (chart attached) RD.
OTHER  COMPLETION  CE  OTHER  Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Compor recompilation.  O5-22-01  Release pkr & tag bottom @ 2709'. POOH w/ tbg.  O5-23-01  TIH w/ 3-7/8" bit & bailer. CO to 2746', POOH w/ baile of the start of the star	THER:: Run MIT/Acidize well/Return to Inj Int details, and give pertinent dates, including estimated date pletions: Attach wellbore diagram of proposed completion  er & bit. 20#. (chart attached) RD. Int TC 420 & 2 drums of TC-405 down tbg. Flushed w/ prod  w/ prod water. Open to pit.
OTHER  COMPLETION  CE  OTHER  Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Compor recompilation.  O5-22-01  Release pkr & tag bottom @ 2709'. POOH w/ tbg.  O5-23-01  TIH w/ 3-7/8" bit & bailer. CO to 2746', POOH w/ baile of the start of the star	THER:: Run MIT/Acidize well/Return to Inj Int details, and give pertinent dates, including estimated date pletions: Attach wellbore diagram of proposed completion  er & bit. 20#. (chart attached) RD. Int TC 420 & 2 drums of TC-405 down tbg. Flushed w/ prod  w/ prod water. Open to pit.
OTHER  12. Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Comport recompilation.  05-22-01 Release pkr & tag bottom @ 2709'. POOH w/ tbg. 05-23-01 TIH w/ 3-7/8" bit & bailer. CO to 2746', POOH w/ baile 05-24-01 Test tbg in hole. Set pkr @ 2601' & tested annulus to 32 06-01-01 RU & pump 500 gals Xylene followed w/ 5 gals Unicher water. SI.  06-06-01 RU & acidize w/ 2000 gals 15% Pentol 300 acid. Flush 06-06-02 Flow & swab back. 06-07-01 Return to injection @ 74 BPD rate @ 860 psi.	THER:: Run MIT/Acidize well/Return to Inj Int details, and give pertinent dates, including estimated date pletions: Attach wellbore diagram of proposed completion  er & bit. 20#. (chart attached) RD. In TC 420 & 2 drums of TC-405 down tbg. Flushed w/ prod  w/ prod water. Open to pit.  OCD ARTESIA  of my knowledge and belief.
OTHER  12. Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Comport recompilation.  05-22-01 Release pkr & tag bottom @ 2709'. POOH w/ tbg. 05-23-01 TIH w/ 3-7/8" bit & bailer. CO to 2746', POOH w/ baile 05-24-01 Test tbg in hole. Set pkr @ 2601' & tested annulus to 32 06-01-01 RU & pump 500 gals Xylene followed w/ 5 gals Unicher water. SI.  06-06-01 RU & acidize w/ 2000 gals 15% Pentol 300 acid. Flush 06-06-02 Flow & swab back. 06-07-01 Return to injection @ 74 BPD rate @ 860 psi.	THER:: Run MIT/Acidize well/Return to Inj Int details, and give pertinent dates, including estimated date pletions: Attach wellbore diagram of proposed completion  er & bit. 20#. (chart attached) RD. Int TC 420 & 2 drums of TC-405 down tbg. Flushed w/ prod  w/ prod water. Open to pit.
OTHER    Completed operations   Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Comport of recompilation.    O5-22-01	THER:: Run MIT/Acidize well/Return to Inj Int details, and give pertinent dates, including estimated date pletions: Attach wellbore diagram of proposed completion  Per & bit. Power of the transport of the trans
OTHER    Completed operations   Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Comport of recompilation.    O5-22-01	THER:: Run MIT/Acidize well/Return to Inj Int details, and give pertinent dates, including estimated date pletions: Attach wellbore diagram of proposed completion  er & bit. 20#. (chart attached) RD. In TC 420 & 2 drums of TC-405 down tbg. Flushed w/ prod  w/ prod water. Open to pit.  OCD ARTESIA  of my knowledge and belief.
OTHER  12. Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Comport recompilation.  05-22-01 Release pkr & tag bottom @ 2709'. POOH w/ tbg. 05-23-01 TIH w/ 3-7/8" bit & bailer. CO to 2746', POOH w/ baile 05-24-01 Test tbg in hole. Set pkr @ 2601' & tested annulus to 32 06-01-01 RU & pump 500 gals Xylene followed w/ 5 gals Unicher water. SI.  06-06-01 RU & acidize w/ 2000 gals 15% Pentol 300 acid. Flush 06-06-02 Flow & swab back. 06-07-01 Return to injection @ 74 BPD rate @ 860 psi.	THER:: Run MIT/Acidize well/Return to Inj Int details, and give pertinent dates, including estimated date pletions: Attach wellbore diagram of proposed completion  Per & bit. Pow. (chart attached) RD. Int TC 420 & 2 drums of TC-405 down tbg. Flushed w/ prod  w/ prod water. Open to pit.  Production Analyst  DATE  6-11-01
OTHER  12. Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Comport recompilation.  05-22-01 Release pkr & tag bottom @ 2709'. POOH w/ tbg. 05-23-01 TIH w/ 3-7/8" bit & bailer. CO to 2746', POOH w/ baile 05-24-01 Test tbg in hole. Set pkr @ 2601' & tested annulus to 32 06-01-01 RU & pump 500 gals Xylene followed w/ 5 gals Unicher water. SI. 06-06-01 RU & acidize w/ 2000 gals 15% Pentol 300 acid. Flush 06-06-02 Flow & swab back. 06-07-01 Return to injection @ 74 BPD rate @ 860 psi.  I hereby certify that the information above is true and complete to the best SIGNATURE  Type or print name Terry Stathem Tele (This space for State use)	THER:: Run MIT/Acidize well/Return to Inj Int details, and give pertinent dates, including estimated date pletions: Attach wellbore diagram of proposed completion  er & bit. 20#. (chart attached) RD. In TC 420 & 2 drums of TC-405 down tbg. Flushed w/ prod  w/ prod water. Open to pit.  OCD ARTESIA  of my knowledge and belief.  Production Analyst DATE 6-11-01  phone No. 915/683-7443
OTHER  12. Describe proposed or completed operations. (Clearly state all pertine of starting any proposed work). SEE RULE 1103. For Multiple Comport recompilation.  05-22-01 Release pkr & tag bottom @ 2709'. POOH w/ tbg. 05-23-01 TIH w/ 3-7/8" bit & bailer. CO to 2746', POOH w/ baile 05-24-01 Test tbg in hole. Set pkr @ 2601' & tested annulus to 32 06-01-01 RU & pump 500 gals Xylene followed w/ 5 gals Unicher water. SI.  06-06-01 RU & acidize w/ 2000 gals 15% Pentol 300 acid. Flush 06-06-02 Flow & swab back. 06-07-01 Return to injection @ 74 BPD rate @ 860 psi.	THER:: Run MIT/Acidize well/Return to Inj Int details, and give pertinent dates, including estimated date pletions: Attach wellbore diagram of proposed completion  Per & bit. Pow. (chart attached) RD. Int TC 420 & 2 drums of TC-405 down tbg. Flushed w/ prod  w/ prod water. Open to pit.  Production Analyst  DATE  6-11-01