

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

U.S. CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

O. C. D.
ARTESIA, OFFICE

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name
2. Name of Operator Santa Rita Exploration Corporation		8. Farm or Lease Name Moonlight 33 West
3. Address of Operator P.O. Box 798, Artesia, New Mexico 88210		9. Well No. #2
4. Location of Well UNIT LETTER <u>G</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>33</u> TOWNSHIP <u>7S</u> RANGE <u>28E</u> N.M.P.M.		10. Field and Pool, or Wildcat Und. San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 3986' GL		12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to plug and abandon well. Will set plugs at the following depths:

60 sxs. from T.D. to 2200'
50 sxs. from 1300' to 1150'
100 sxs. from 750' to 650'
50 sxs. plug across 8 5/8" casing shoe at 418'
Tag 8 5/8" plug
20 sxs. plug at surface

Will then clean location and notify N.M.O.C.D. for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Donald R. Cray TITLE Vice-President of Oper. DATE 1/18/82

APPROVED BY Walter Williams TITLE Oil and Gas Inspector DATE JAN 20 1982

CONDITIONS OF APPROVAL, IF ANY: