

OIL CONSERVATION DIVISION

P. O. BOX 2203
SANTA FE, NEW MEXICO 87501

Form O-103
Revised 10-1-79

NAME OF OPERATOR	
DISTRICT	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

SEP 16 1981

5a. Indicate Type of Lease
State ☐ Free ☒

5. State Oil & Gas Lease No.

7. Unit Agreement Name

8. Farm or Lease Name

O'Brien "GG"

9. Well No.

1

10. Field and Pool, or Wildcat
Twin Lakes-San Andres
Assoc.

12. County

Chaves

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR INDIVIDUALS TO DRILL OR TO REFINER OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT WITH FORM C-101 FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator

Stevens Operating Corporation

Address of Operator

P. O. Box 2203, Roswell, New Mexico 88201

Location of Well

UNIT LETTER D 330 FEET FROM THE North LINE AND 330 FEET FROM

THE West LINE, SECTION 8 TOWNSHIP 9S RANGE 29E N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)

3916.2 GR, 3921.2 KB

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

COMMENCE DRILLING OPNS. ☒

PLUG AND ABANDONMENT ☐

ILL OR ALTER CASING ☐

CHANGE PLANS ☐

CASING TEST AND CEMENT JOBS ☒

OTHER Perforations & Treatment ☒

OTHER ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-21-81 Spud. Ran 3 joints 8 5/8" 20# surface casing. Set in cement at 130' with 75 sacks Class "C", 1% CaCl₂. Circulate 16 sacks. WOC 18 hrs. Pressure up 1000# for 30 minutes logging no pressure decrease.

8-29-81 Ran 71 joints 4 1/2" 9.5# casing, set in cement at 2860' w/200 sacks self stress, 3% CaCl₂. WOC 18 hrs. Pressure up 1000# for 30 minutes logging no pressure decrease.

9-1-81 Perforate at 2732.5, 33, 33.5, 34, 38, 38.5, 39, 2741, 41.5, 42, 2756, 56.5, 57, 59.5, 60, 60.5, 64.5, 65, 65.5. Ran 87 joints 2 3/8" tubing, spot 2 bbls 28% acid at 2768'. Pull 5 joints, acidize w/9000 gals 28% and 50 balls.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED: *Lois G. Turner*

TITLE: President

DATE: 9-17-81

APPROVED BY: *W. O. [Signature]*

TITLE: [Signature]

DATE: SEP 16 1981

CONDITIONS OF APPROVAL, IF ANY: