

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

RECEIVED

OCT - 5 1981

O. C. D.  
ARTESIA, OFFICE

Form C-103  
Revised 10-1-78

3a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	
3. State Oil & Gas Lease No. LG 5573	
7. Unit Agreement Name	
8. Farm or Lease Name Macho State	
9. Well No. 2	
10. Field and Pool, or Wildcat Wildcat ABO	
12. County Chaves	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER-	2. Name of Operator Transwestern Gas Supply Company
3. Address of Operator P. O. Box 2521, 1HC 3740, Houston, Texas 77001	4. Location of Well UNIT LETTER <u>F</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>33</u> TOWNSHIP <u>6S</u> RANGE <u>23E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4063 GR	12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Set 40' of 14" conductor with rathole machine and grouted to surface. Spud well with 12-1/4" hole at 0030 9-24-81. Drilling with air 1065'. Pipe stuck, worked free. POOH, dump 9 yards redi-mix. Drill redi-mix 498'-730'. Wash and ream to 850'. Pipe stuck, jarred free. GIH open ended to 850', plugged pipe. Unable to get deeper, prepare to run 8-5/8" casing.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Manager, U.S. Onshore Prod. DATE 09/29/81

APPROVED BY [Signature] TITLE SUPERVISOR, DISTRICT II DATE OCT 14 1981

CONDITIONS OF APPROVAL, IF ANY: