

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

C151
DP

Form C-103
Revised 10-1-79

30. Indicate Type of Lease	
State ☒	Fee ☐
31. State Oil & Gas Lease No.	
STA-LG-566-1	
7. Unit Agreement Name	
NA	
8. Farm or Lease Name	
Grynberg 16 State	
9. Well No.	
1	
10. Field and Pool, or Wharft	
Pecos Slope Abo Gas	
12. County	
Chaves	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" FORM C-101 FOR SUCH PROPOSALS.

1. OIL ☐ GAS ☒ WELL ☐ OTHER ☐		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Jack J. Grynberg		Grynberg 16 State
3. Address of Operator		9. Well No.
5000 South Quebec, Suite 500, Denver, CO 80237		1
4. Location of Well		10. Field and Pool, or Wharft
UNIT LETTER <u>P</u> <u>660'</u> FEET FROM THE <u>South</u> LINE AND <u>660'</u> FEET FROM		Pecos Slope Abo Gas
THE <u>East</u> LINE, SECTION <u>16</u> TOWNSHIP <u>5S</u> RANGE <u>24E</u> NMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
3988 KB		Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well will be plugged as follows:

1. Set CIBP @ 3550 and cap w/35' cement.
2. Perf 4-1/2 at 920' and equalize 75 sx plug inside and outside 4-1/2 casing.
3. Cut off casing strings 2' below ground.
4. Lay 10 sk plug inside 4-1/2 casing at surface.
5. Leave salt gel mixed w/25#/bbl brine between plugs.
6. Install dry hole marker 4' above ground level.
7. Cut off anchors and flowlines 1' below ground.
8. Clean and level locations.

10-3/4 @ 860'
4-1/2 @ 4150
PBTB 4076
TOC 960
Perfs 3592-3763
Top Glonetta @ 1430

WORK TO BEGIN WITHIN 60 DAYS,
TJLW

RECEIVED
OCD - ARTESIA

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED K R Henderson TITLE Engineer DATE 2/11/98
APPROVED BY [Signature] TITLE DATE 3-2-98
CONDITIONS OF APPROVAL, IF ANY: