

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

JUL 28 1993

C.C.D.

WELL API NO.
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. LH-181-3
7. Lease Name or Unit Agreement Name New Mexico State "36"
8. Well No. 1
9. Pool name or Wildcat Hagerman Strawn Gas
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3453' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: OIL WELL ☐ GAS WELL ☒ OTHER ☐
2. Name of Operator Lynx Petroleum Consultants, Inc.
3. Address of Operator P.O. Box 1979, Hobbs, NM 88241
4. Well Location Unit Letter <u>F</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>36</u> Township <u>13S</u> Range <u>26E</u> NMPM <u>Chaves</u> County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set C.I.B.P. at 6500' with 3 sxs cement on top.
2. Load hole with 10 ppg mud.
3. * Cut and pull 4 1/2" casing at + 4200'. 4605
4. Spot 30 sxs cement casing stub plug 4150-~~4250~~' Tag plug.
5. Spot 40 sxs cement plug 2400-2500'.
6. Spot 35 sxs cement plug 1575-1675'. Tag plug.
7. Spot 30 sxs cement plug 335-435'.
8. Spot 10 sxs cement surface plug.
9. Install Dry Hole Marker and clean location.

(Wellbore Sketches Attached)

Notify N.M.O.C.C. in sufficient time to witness

* Plug at 5200-5450

Plugging

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Marc Wise TITLE President DATE 7/22/93
TYPE OR PRINT NAME Marc Wise TELEPHONE NO 392-6950

(This space for Sign Use)

APPROVED BY [Signature] TITLE Field Rep DATE 8/26/93
CONDITIONS OF APPROVAL IF ANY

6" - 3000 psi Flange

CURRENT WELLBORE STATUS

7/21/93

385' - 13 3/8", 48# Casing

Cemented w/350 sxs. Circulated 10 sxs to surface.

1625' - 8 5/8", 24# Casing

Cemented w/910 sxs. Circulated 35 sxs to surface.

2 3/8", 4.7#, N-80, 8rd Tubing

T.O.C. @ 5260'

4 1/2" Casing Detail

0'-885' 21 jts 11.6# J-55

885'-5906' 118 jts 10.5# J-55

5906'-6918' 24 jts 11.6# J-55

Baker Model R @ 6495'

6581' ←
Perfs

6660' ←

6918' - 4 1/2", 10.5# & 11.6#, J-55, Casing

Cemented w/475 sxs


P.B.T.D. @ 6846'

T.D. @ 6918'

Elevation = 3453' GR
KB = +13'

LYNX PETROLEUM
NEW MEXICO STATE "36"
1980' FNL & 1980' FWL
SECTION 36, T-13S, R-26E
CHAVES COUNTY, NEW MEXICO

PROPOSED PLUG & ABANDONMENT
7/21/93



10 sxs Cement Surface Plug

30 sxs Cement Plug (335'-435')

385' - 13 3/8", 48# Casing

Cemented w/350 sxs. Circulated 10 sxs to surface.

35 sxs Cement Plug (1575'-1675')

1625' - 8 5/8", 24# Casing

Cemented w/910 sxs. Circulated 35 sxs to surface.

40 sxs Cement Plug (2400'-2500')

30 sxs Cement Casing Stub Plug (4150'-4250')

4 1/2" Casing Cut and Pulled @ 4200' ±

T.O.C. @ 5260'

C.I.B.P. @ 6500' w/3 sxs cement

6581' ←
Perfs

6660' ←

6918' - 4 1/2", 10.5# & 11.6#, J-55, Casing

Cemented w/475 sxs

P.B.T.D. @ 6846'

T.D. @ 6918'

Elevation = 3453' GR
KB = +13'

LYNX PETROLEUM
NEW MEXICO STATE "36"
1980' FNL & 1980' FWL
SECTION 36, T-13S, R-26E
CHAVES COUNTY, NEW MEXICO