

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

AUG 07 1991

O. C. D.

ARTESIA, OFFICE

WELL API NO.

30-005-61331

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

LG-563

7. Lease Name or Unit Agreement Name

Smernoff NL State

8. Well No.

3

9. Pool name or Wildcat

Pecos Slope- Abo Gas

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☐

OTHER P&A

2. Name of Operator

YATES PETROLEUM CORPORATION

3. Address of Operator

105 South 4th St., Artesia, NM 88210

4. Well Location

Unit Letter D : 660 Feet From The North Line and 660 Feet From The West Line

Section 2

Township 5S

Range 24E

NMPM

Chaves

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

We propose to Plug and Abandon well as follows:

1. Set cast iron bridge plug and 35' cement at 3550'. (2.5 sx class "C")
2. Cut and pull approx. 2400' 4-1/2" casing.
3. 30 sx class "C" cement 2450'-2350'. Tag plug.
4. 30 sx class "C" cement 1570'-1470'. Tag plug.
5. 35 sx class "C" 930'-810' tag plug.
6. 10 sx class "C" 37' to surface.
7. Cut off well head. Weld on dry hole marker.

Get Defensen All Plugs

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Juanita Goodlett

TITLE

Production Supervisor

DATE

8-6-91

TELEPHONE NO. 505/748-147

TYPE OR PRINT NAME

Juanita Goodlett

(This space for State Use)

APPROVED BY

[Signature]

TITLE

Field Rep

DATE

8/15/91

CONDITIONS OF APPROVAL, IF ANY:

Plugging