

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

811 South First, Artesia, NM 87210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO.  
30-005-61344

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.  
STA-NM-LG-566-1

7. Lease Name or Unit Agreement Name:  
Grynberg 32 State

8. Well No.  
3

9. Pool name or Wildcat  
Abo

10. Elevation (Show whether DR, RKB, RT, GR, etc.)  
4164 KB

SUNDY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLOG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
Oil Well ☐ Gas Well ☒ Other

2. Name of Operator  
Jack J. Grynberg

3. Address of Operator  
5299 DTC Blvd., Suite 500 Greenwood Village, CO 80111

4. Well Location  
Unit Letter N : 660 feet from the South line and 1980 feet from the West line  
Section 32 Township 5S Range 24E NMPM County Chaves

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
MULTIPLE COMPLETION <input type="checkbox"/>	OTHER: <input type="checkbox"/>
OTHER: <input type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

See attached reports.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ken McKinney TITLE Prod. Manager DATE 7/31/2002

Type or print name Ken McKinney Telephone No. 303-850-7490  
(This space for State use)

APPROVED BY [Signature] TITLE Field Rep DATE JAN 10 2003

Conditions of approval, if any:

Post P&A

MAYO MARRS CASING PULLING INC.  
BOX 863  
KERMIT, TEXAS 79745

JACK J. GRYNBERG

Lease: GRYNBERG 32 STATE # 3

Project: P & A – CEMENTING REPORT

---

06-20-2002 - SET CIBP @ 3,725' – DUMP 50' CEMENT ON TOP – 3,675'

06-21-2002 – SPOT 90 SXS @ 1056' - 823' TAGGED

06-21-2002 - PULLED 1000' OF 4 ½" CASING

06-19-2002 - SPOT 15 SXS @ 60' TO SURFACE

INSTALL DRY HOLE MARKER

CIRCULATE 10# MUD

MAYO MARRS CASING PULLING INC.

GRYNBERG PETROLEUM COMPANY

Lease: GRYNBERG 32 STATE # 3

Project: P & A

---

6-20-02

NOTIFY BLM – MOVE IN RIG UP – DIG & LINE WORKING PIT - NUBOP – POOH WITH 116 JOINTS 2 3/8" TUBING -RIH & SET CIBP @ 3725' – DUMP 35' CEMENT ON TOP – RIH WITH TUBING & CIR. 10# MUD – POOH & SPOT 25 SXS @ 2144' --1783' - POOH – ND WELLHEAD – RIH & CUT CASING @ 1000' – SHUT DOWN

6-21-02

POOH & LAY DOWN 24 JOINTS 4 1/2" CASING – RIH & SPOT 90 SXS @ 1056' – POOH – WOC – RIH & TAG @ 823' – POOH & SPOT 15 SXS @ SURFACE - DIG OUT & CUT OFF WELLHEAD & ANCHORS – INSTALL DRY HOLE MARKER - RIG DOWN – MOVE OUT – LEVEL PIT & CELLAR

SALVAGE = 3,596' OF 2 3/8" TUBING = 116 JOINTS

1,000' OF 4 1/2" CASING = 24 JOINTS