Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

DO Drawer DD, Artesia, NM 88210

OIL CONSERVATION DIFFEREN
P.O. Box 2088
Santa Fe, New Mexico 87564288 1992

WELL API NO.		
30-005-61378	 	
5. Indicate Type of Lease		1273
STATE	FEE	XX

	Q_{i}	STATE FEE XX
STRICT III 00 Rio Brazos Rd., Aztec, NM 87410	ARTERIA CENCE	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON V DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEF DIFFERENT RESERVOIR. USE "APPLICATION FOR (FORM C-101) FOR SUCH PROPOSALS.)	PEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
Type of Well: OIL GAS WELL OTHER P&A	A.	Western Com
Name of Operator (ATES PETROLEUM CORPORATION		8. Well No.
Address of Operator LO5 South 4th St., Artesia, NM 88210		9. Pool name or Wildcat Pecos Slope Abo
Well Location Unit Letter M : 660 Feet From The South	Line and 660	
Section 19 Township 6S 10. Elevation (Show whe	Range 25E ther DF, RKB, RT, GR, etc.)	NMPM Chaves County
Check Appropriate Box to Indica NOTICE OF INTENTION TO:		Report, or Other Data SSEQUENT REPORT OF:
HOHOL OF MILLION FOR	1	
FORM REMEDIAL WORK PLUG AND ABANDON	X REMEDIAL WORK	ALTERING CASING
FORM REVIEDIAL WORK	X REMEDIAL WORK COMMENCE DRILLIN	
PORARILY ABANDON CHANGE PLANS		G OPNS. PLUG AND ABANDONMENT
MPORARILY ABANDON CHANGE PLANS CLOR ALTER CASING	COMMENCE DRILLIN	G OPNS. PLUG AND ABANDONMENT
MPORARILY ABANDON CHANGE PLANS L OR ALTER CASING HER: Revised P&A procedure	COMMENCE DRILLIN CASING TEST AND C OTHER:	G OPNS. PLUG AND ABANDONMENT
PORARILY ABANDON CHANGE PLANS LOR ALTER CASING Describe Proposed or Completed Operations (Clearly state all pertinent detail work) SEE RULE 1103. Propose to plug and abandon well as follows: 1. Set CIBP at 3363' and cap w/35' of control of the control of th	COMMENCE DRILLIN CASING TEST AND C OTHER: ils, and give pertinent dates, incl. ows; ement.	G OPNS. PLUG AND ABANDONMENT EMENT JOB uding estimated date of starting any proposed
APORARILY ABANDON CHANGE PLANS LOR ALTER CASING HER: Revised P&A procedure Describe Proposed or Completed Operations (Clearly state all pertinent detail work) SEE RULE 1103. Propose to plug and abandon well as followed to the state of	COMMENCE DRILLIN CASING TEST AND C OTHER: ils, and give pertinent dates, incl. ows; ement.	G OPNS. PLUG AND ABANDONMENT
Describe Proposed or Completed Operations (Clearly state all pertinent detail work) SEE RULE 1103. Propose to plug and abandon well as followed: 1. Set CIBP at 3363' and cap w/35' of collowed: 2. Circulate hole w/mud laden fluid. 3. Spot 25 sx plug 2680-2780'. 4. Cut 4½" casing at 1800' and pull. 5. Load hole w/mud laden fluid. 6. Spot 35 sx plug 1700-1850', tag this 7. Spot 25 sx plug 850-950'. 8. Spot 10 sx surface plug. 9. Install dry hole marker. 10. Clean & abandon location. Chuck Morgan of YPC, received verbal perm	COMMENCE DRILLIN CASING TEST AND C OTHER: ils, and give pertinent dates, incl. ows; ement.	GOPNS. PLUG AND ABANDONMENT EMENT JOB uding estimated date of starting any proposed
POPPARILY ABANDON CHANGE PLANS LOR ALTER CASING Describe Proposed or Completed Operations (Clearly state all pertinent detail work) SEE RULE 1103. Propose to plug and abandon well as followed to the control of the	COMMENCE DRILLIN CASING TEST AND COMMENCE OTHER: ils, and give pertinent dates, incl. ows; ement. plug. North	GOPNS. PLUG AND ABANDONMENT DEMENT JOB Demonstrated date of starting any proposed Williams, NMOCD, Artesia, NM to
PORARILY ABANDON CHANGE PLANS LOR ALTER CASING Describe Proposed or Completed Operations (Clearly state all pertinent detail work) SEE RULE 1103. Propose to plug and abandon well as follower. 1. Set CIBP at 3363' and cap w/35' of color	COMMENCE DRILLIN CASING TEST AND CO X OTHER: ils, and give pertinent dates, incl ows; ement. plug. None ission from Gary	GOPNS. PLUG AND ABANDONMENT DEMENT JOB Demonstrated date of starting any proposed Williams, NMOCD, Artesia, NM to

CONDITIONS OF APPROVAL, IF ANY: