Some 3: Conject To Appropriate Der B 9:70, Conject To Appropriate Der Dir Der B 9:70, Conject To Appropriate Der Dir Der B 9:70, Conject To Appropriate Der Dir Der		C'	CF		
Items in the should be integed by the out of the set of t	Submit 3 Copies To Appropriate District 0 10 State of New Moving		H.		
Densition Bised First, Arcsis, MM 8210 (M)	District 1 1625 N. French Dr., Hobbs, WM 88240	rai Resources	WELL API NO.	Revised March 25, 1999	
Date time Image in a state in the image in the ima		DIVISION	30-005-61382-	-61395	
1202 Statement Dr., Sight Fr., MPO State Ont & Construction Constructin Construction Construction Constructin Const	District III 1220 South St. Francis Dr.				
SUNDRY ANDRY ANDRY ANDRY AND RELOCATION OF LUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR FRANT" (FORM C-100) FOR SUCH Acme Com 1. Type of Well: Oil Well: Or To the France Pecos Stope Abo 4. Well Location Unit Letter O: 640 for Elevation (Show whether DR, RKB, RT, GR, ecc.) 3.72 GR 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data Section 20 Temporarely and North Comparison REMEIAL WORK PERFORM REMEDIAL WORK PLUG AND ABANDON REMEOIAL WORK COMMENCE DRILLING OPNS. PULL OR ALTER CASING MULTIPLE Cold Andry State and State and State and State and State State and State and State and State and State and State and Stat	1000 Rio Brazos Rd., Azteo, NM 874Ro ARTESIA District IV				
SUNDRY ANDRY ANDRY ANDRY AND RELOCATION OF LUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR FRANT" (FORM C-100) FOR SUCH Acme Com 1. Type of Well: Oil Well: Or To the France Pecos Stope Abo 4. Well Location Unit Letter O: 640 for Elevation (Show whether DR, RKB, RT, GR, ecc.) 3.72 GR 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data Section 20 Temporarely and North Comparison REMEIAL WORK PERFORM REMEDIAL WORK PLUG AND ABANDON REMEOIAL WORK COMMENCE DRILLING OPNS. PULL OR ALTER CASING MULTIPLE Cold Andry State and State and State and State and State State and State and State and State and State and State and Stat	1220 S. St. Francis Dr., Santa Fe, NMY 37505			us Leuse 110.	
DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH Acme Com 1. Type of Well: Other 7. Well No. 2. Name of Operator #12 3. Address of Operator #12 3. Address of Operator 8. Pool name or Wildcat Yets Petroleum Corporation 8. Pool name or Wildcat 105 S. 4 th Steet Attesio, NM 88210 4. Well Location 8. Pool name or Wildcat Unit Letter 0 : 660 20 Township 8S Range 26E NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDON PERFORM REMEDIAL WORK PLUG AND ABANDON PULL OR ALTER CASING CHANGE PLANS OTHER: 0 OCHARGE Proposed or completed operations. (Clearly state all permont detais, and give periment dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recomplation. Propose to temporarily abandon this well to hold if for future deepening. Proposes to temporarily abandon this well is los of get per bbi. Pressure test casing to 500 psi and record chart for 30 minutes. <td colspan="2">SUNDRY NOTICES AND REPORTS ON WELLS</td> <td>7. Lease Name or</td> <td>Unit Agreement Name:</td>	SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or	Unit Agreement Name:	
1. Type of Well: Out Well Gas Well X Other . 2. Name of Operator Yetes Petroleum Corporation . 3. Address of Operator Yetes Petroleum Corporation . 3. Address of Operator 8. Pool name or Wildcat Pecos Slope Abo 4. Well Location Unit Letter O : 660 feet from the South inc and 1980 feet from the East ince Section 20 Township 8S Range 26E NMPM Chaves County 10. Elevation (Show whether DR, RKB, RT, GR, etc.) . 3.1. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDON VELLOR ALTER CASING MULTIPLE COMMENT JOB PULL OR ALTER CASING MULTIPLE COMPLETION COMPLETION CEMENT JOB OTHER: OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Notify OCD 24 hours before commending operations. Yoties proposes to temporarily obandon this well to hold if for future deepening. Propose to temporarily obandon this well to hold if for future deepening. <td< td=""><td>DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR</td><td>OR SUCH</td><td colspan="3">Acme Com</td></td<>	DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR	OR SUCH	Acme Com		
2. Name of Operator 7. Well No. Yetes Petroleum Corporation #12 3. Address of Operator 8. Pool name or Wildcat 105 S. 4 th Street Artesia, NM 88210 4. Well Location Interview Unit Letter 0 20 Township 85 Range 26E NMPM Charves County 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3732 GR 11. Check Appropriate Box to Inforacte Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PERFORM REMEDIAL WORK CASING PULL OR ALTER CASING PULL OR ALTER CASING PULL OR ALTER CASING COMPLETION Completion Charge volume to this well, to hold it for future deepening. Propose to temporative donorthis well, as follows: POOH with tog. Set CIBP of 4535'. Cap with 35' of cement. Load the hole with 10 pop bine plugging mud with 25 lbs of gel per bbl. Pressure last casing to 500 psi and record chart for 30 minutes. File chart with the OCD. TTTLE					
Yates Petroleum Corporation #12 3. Address of Operator 8. Pool name or Wildcat 105 S. 4 th Street Artesia, NM 88210 8. Pool name or Wildcat 4. Well Location Vint Letter 0. : 660 feet from the South line and 1980 feet from the East line Section 20 Township 85 Range 26E NMPM Chaves County 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3732' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. ALTERING ABANDONMENT PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. ABANDONMENT PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. ABANDONMENT PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. ABANDONMENT PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. ABANDONMENT PUL OR ALTER CASING CHANGE PLANS COMPLETION CEMENT JOB OTHER:					
3. Address of Operator 8. Pool name or Wildart 105 S. 4 th Street Artesia, NM 88210 Pecos Slope Abo 4. Well Location Unit Letter O : 660 feet from the South line and 1980 feet from the East line Section 20 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3732 'GR County 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING COMPLETION CEMENT JOB Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompliation. Notify the OCD 24 hours before commencing operations. Yeats proposes to temporarily abandon this well as follows: POOH with the DCD. Notify OCD 24 hrs., prior to test. Set CIBP of 4335'. Cap with 35' of cement. Locad the hole with 10 ppg bine plugging mud with 25 lbs of gel per bbl. Pressure test casing to 500 psi and record chort for 30 minutes. File chort with the OCD. TIT					
4. Well Location Unit Letter O: 660 feet from the South ine and 1980 feet from the East ine Section 20 Township 85 Range 26E NMPM Chaves County 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3732' GR Internet of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: Internet of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK Internet of Notice, Report or Other Data MOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: Internet of Notice, Report or Other Data PULL OR ALTER CASING Other Data Internet of Notice, Report or Other Data PULL OR ALTER CASING MULTIPLE CASING TEST AND PULL OR ALTER CASING MULTIPLE CASING TEST AND Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recomplation. Notify the OCD 24 hours before commencing operations. Yates proposes to temporarily abandon this well, to hold if for future deepening. Propose to temporarily a					
Unit Letter O : 660 feet from the _South line and _1980 feet from the _East line Section 20 Township 85 Range 26E NMPM Chaves County 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3732' GR	105 S. 4 th Street Artesia, NM 88210		Pecos Slope Abo		
Section 20 Township 85 Range 26E NMPM Chaves County 10. Elevation (Show whether DR, REB, RT, GR, etc.) 3732' GR 3732' GR 3732' GR 3732' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. ALMED AND PULL OR ALTER CASING MULTIPLE CASING TEST AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND ABANDONMENT Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Notify the OCD 24 hours before commencing operations. Yates proposes to temporarily abandon this well, to hold it for future deepening. Propose to temporarily abandon this well as follows: POOH with tbg. Stot Cap with 35' of cement. Load the hole with 10 ppg brine plugging mud with 25 lbs of gel per bbl. Pressure lest casing to 500 psi and record charl for 30 minules. Sto5-748-1283	4. Well Location				
Section 20 Township 85 Range 26E NMPM Chaves County 10. Elevation (Show whether DR, REB, RT, GR, etc.) 3732' GR 3732' GR 3732' GR 3732' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. ALMED AND PULL OR ALTER CASING MULTIPLE CASING TEST AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND ABANDONMENT Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Notify the OCD 24 hours before commencing operations. Yates proposes to temporarily abandon this well, to hold it for future deepening. Propose to temporarily abandon this well as follows: POOH with tbg. Stot Cap with 35' of cement. Load the hole with 10 ppg brine plugging mud with 25 lbs of gel per bbl. Pressure lest casing to 500 psi and record charl for 30 minules. Sto5-748-1283					
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3732' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING COMPLETION OTHER: OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Notify the OCD 24 hours before commencing operations. Yates proposes to temporarily abandon this well, to hold it for future deepening. Propose to temporarily abandon this well as follows: POOH with tag. Set CIBP at 4535'. Cap with 35' of cement. Load the hole with 10 ppg brine plugging mud with 25 lbs of gel per bbl. Pressure test casing to 500 psi and record chart for 30 minutes. Stof5-748-1283 File chart with the OCD. Stof and record chart for 30 minutes. <t< td=""><td colspan="5">Unit Letter <u>O</u>: 660 feet from the SOUTH line and 1980 feet from the EQST line</td></t<>	Unit Letter <u>O</u> : 660 feet from the SOUTH line and 1980 feet from the EQST line				
3732' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Notify the OCD 24 hours before commencing operations. Yates propose to temporarily abandon this well, to hold it for future deepening. Propose to temporarily abandon this well as follows: POOH with fbg. Set CIBP of 4535'. Cap with 35' of cement. Load the hole with 10 ppg brine plugging mud with 25 lbs of gel per bbl. Pressure test casing to 500 psi and record chart for 30 minutes. Notify OCD 24 hrs. prior to test.	1 0			County	
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON PULL OR ALTER CASING MULTIPLE COMPLETION COMPLETION CEMENT JOB OTHER: OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompliation. Notify the OCD 24 hours before commencing operations. Yates proposes to temporarily abandon this well, to hold it for future deepening. Propose to temporarily abandon this well as follows: POOH with 10g. Set CIBP at 4535'. Cap with 35' of cement. Load the hole with 10 pp bine plugging mud with 25 lbs of gel per bbl. Pressure test casing to 500 psi and record chart for 30 minutes. File chart with the OCD.	(時間には時間においておける)に、「「いけ」が、時間には時間には「「「」」、「」、「」、「」、「」、「」、「」、「」、「」、「」、「」、「」、「				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND PULL OR ALTER CASING MULTIPLE CASING TEST AND PLUG AND ABANDON OTHER: OTHER: OTHER: OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Notify the OCD 24 hours before commencing operations. Yates proposes to temporarily abandon this well, to hold it for future deepening. Propose to temporarily abandon this well as follows: POOH with tbg. Set CIBP at 4535'. Cap with 35' of cement. Load the hole with 10 ppg brine plugging mud with 25 lbs of gel per bbl. Pressure test casing to 500 psi and record chart for 30 minutes. Notify OCD 24 hrs. prior to test. File chart with the OCD. S05-748-1283 Thereby certify that the information above is true and complete to the best of my knowledge DATE May 3, 2002 Type or print name Susan Hengin Telephone No. 505-748-1471 (This space for State use) APPPROVED BY TITLE Functionand Participante Participante Participante Partindite Participante Participante Partindite Par					
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB ABANDONMENT OTHER: OTHER: Image: Completed operations. Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed or completed operations. Notify the OCD 24 hours before commencing operations. Yates proposes to temporarily abandon this well, to hold it for future deepening. Propose to temporarily abandon this well as follows: POOH with tog. Set CIBP at 4535'. Cap with 35' of cement. Load the hole with 10 ppg bine plugging mud with 25 lbs of gel per bbl. Pressure test casing to 500 psi and record chart for 30 minutes. Notify OCD 24 hrs. prior to test. SIGNATURE Mutype TITLE Engineering Technician DATE May 3, 2002 Type or print name Susan Hengin Telephone No. 505-748-1471 (This space for State use) TITLE Engineering Technician DATE 9 2002	NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
TEMPORARILY ABANDON X CHARGE PLANS COMMENCE DRILLING OPNS. ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB ABANDONMENT OTHER: OTHER: Image: Complete operations. Casing other completion of proposed completion or recompilation. Notify the OCD 24 hours before commencing operations. Yates proposes to temporarily abandon this well, to hold if for future deepening. Propose to temporarily abandon this well, as follows: POOH with tbg. Set CIBP of 4535'. Cap with 35' of cement. Load the hole with 10 ppg brine plugging mud with 25 lbs of gel per bbl. Notify OCD 24 hrs. prior to test. File chart with the OCD. Sot 748-1283 Thereby certify that the information above is true and complete to the best of my knowners Sot 748-1283 Thereby certify that the information above is true and complete to the best of my knowners Telephone No. 505-748-1471 (This space for State use) TITLE Engineering Technician APPPROVED BY TITLE Walk 9 2002	PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK		CASING	
PULL OR ALTER CASING COMPLETION CEMENT JOB OTHER: OTHER: OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Notify the OCD 24 hours before commencing operations. Yates proposes to temporarily abandon this well, to hold it for future deepening. Propose to temporarily abandon this well as follows: POOH with fbg. Set CIBP at 4535 ¹ . Cap with 35 ¹ of cement. Load the hole with 10 ppg brine plugging mud with 25 lbs of gel per bbl. Pressure test casing to 500 psi and record chart for 30 minutes. File chart with the OCD. Notify OCD 24 hrs. prior to test. 505-748-1283 Thereby certify that the information above is true and complete to the best of my know reception SIGNATURE Susan Herein Telephone No. 505-748-1471 (This space for State use) TITLE APPPROVED BY TITLE	TEMPORARILY ABANDON X CHANGE PLANS	COMMENCE DRILI	LING OPNS.		
Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Notify the OCD 24 hours before commencing operations. Yates proposes to temporarily abandon this well, to hold it for future deepening. Propose to temporarily abandon this well as follows: POOH with tbg. Set CIBP at 4535'. Cap with 35' of cement. Load the hole with 10 ppg brine plugging mud with 25 lbs of gel per bbl. Pressure test casing to 500 psi and record chart for 30 minutes. File chart with the OCD. Notify OCD 24 hrs. prior to test. 505-748-1283 I hereby certify that the information above is true and complete to the best of my knowing. SIGNATURE Jump TITLE Engineering Technician DATE May 3, 2002 Type or print name Susan Henpin APPPROVED BY TITLE			D		
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. Notify the OCD 24 hours before commencing operations. Yates proposes to temporarily abandon this well, to hold it for future deepening. Propose to temporarily abandon this well as follows: POOH with tbg. Set CIBP at 4535'. Cap with 35' of cement. Load the hole with 10 ppg brine plugging mud with 25 lbs of gel per bbl. Pressure test casing to 500 psi and record chart for 30 minutes. File chart with the OCD. Notify OCD 24 hrs. prior to test. 505-748-1283 I hereby certify that the information above is true and complete to the best of my know receptore SIGNATURE Jupper or print name Susan Herpin Type or print name Susan Herpin Tittle APPPROVED BY	OTHER:	OTHER:			
recompilation. Notify the OCD 24 hours before commencing operations. Yates proposes to temporarily abandon this well, to hold it for future deepening. Propose to temporarily abandon this well as follows: POOH with tbg. Set CIBP at 4535'. Cap with 35' of cement. Load the hole with 10 ppg brine plugging mud with 25 lbs of gel per bbl. Pressure test casing to 500 psi and record chart for 30 minutes. File chart with the OCD. Type or print name Susan Herpin TITLE Engineering Technician DATE May 3, 2002 Type or print name Susan Herpin APPPROVED BY					
Notify the OCD 24 hours before commencing operations. Yates proposes to temporarily abandon this well, to hold it for future deepening. Propose to temporarily abandon this well as follows: POOH with tbg. Set CIBP at 4535'. Cap with 35' of cement. Load the hole with 10 ppg brine plugging mud with 25 lbs of gel per bbl. Pressure test casing to 500 psi and record chart for 30 minutes. File chart with the OCD. Notify OCD 24 hrs. prior to test. 505-748-1283 I hereby certify that the information above is true and complete to the best of my know receptor SIGNATURE May 3, 2002 Type or print name Susan Hengin THELE APPPROVED BY					
Propose to temporarily abandon this well as follows: POOH with tbg. Set CIBP at 4535'. Cap with 35' of cement. Load the hole with 10 ppg brine plugging mud with 25 lbs of gel per bbl. Pressure test casing to 500 psi and record chart for 30 minutes. File chart with the OCD. Notify OCD 24 hrs. prior to test. 505-748-1283 I hereby certify that the information above is true and complete to the best of my know house SIGNATURE	-				
POOH with tbg. Set CIBP at 4535'. Cap with 35' of cement. Load the hole with 10 ppg brine plugging mud with 25 lbs of gel per bbl. Pressure test casing to 500 psi and record chart for 30 minutes. File chart with the OCD. File chart with the OCD. Notify OCD 24 hrs. prior to test. 505-748-1283 I hereby certify that the information above is true and complete to the best of my know regerer. SIGNATURE <u>Mar Mappine</u> TITLE <u>Engineering Technician</u> DATE <u>May 3, 2002</u> Type or print name <u>Susan Henpine</u> (This space for State use) APPPROVED BYTITLE <u>TITLE</u> <u>DATE</u> <u>May 9 2002</u>					
Set CIBP at 4535'. Cap with 35' of cement. Load the hole with 10 ppg brine plugging mud with 25 lbs of gel per bbl. Pressure test casing to 500 psi and record chart for 30 minutes. File chart with the OCD. Notify OCD 24 hrs. prior to test. 505-748-1283 I hereby certify that the information above is true and complete to the best of my know to ge and SIGNATURE I hereby certify that the information above is true and complete to the best of my know to ge and SIGNATURE I hereby certify that the information above is true and complete to the best of my know to ge and SIGNATURE I hereby certify that the information above is true and complete to the best of my know to ge and SIGNATURE I hereby certify that the information above is true and complete to the best of my know to ge and SIGNATURE I hereby certify that the information above is true and complete to the best of my know to ge and SIGNATURE May 3, 2002 Type or print name Susan Herpin Telephone No. 505-748-1471 (This space for State use) May 3 2002 APPPROVED BY TITLE					
Pressure test casing to 500 psi and record chart for 30 minutes. File chart with the OCD. Notify OCD 24 hrs. prior to test. 505-748-1283 I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE					
File chart with the OCD. Notify OCD 24 hrs. prior to test. SIGNATURE May 3, 2002 Type or print name Susan Herpin Title Engineering Technician DATE May 3, 2002 Type or print name Susan Herpin Title Title APPPROVED BY TITLE					
test. 505-748-1283 I hereby certify that the information above is true and complete to the best of my knowledge and the set of my knowledge and the		iutes. N	otify OCD 24	hrs prior to	
505-748-1283 I hereby certify that the information above is true and complete to the best of my knowledge and the set of my knowledge and					
SIGNATURE Hitch III upper TITLE Engineering Technician DATE May 3, 2002 Type or print name Susan Henpin Telephone No. 505-748-1471 (This space for State use) TITLE Juil upper DATE May 3, 2002 APPPROVED BY TITLE Juil upper DATE 9 2002				1283	
SIGNATURE Hitch III upper TITLE Engineering Technician DATE May 3, 2002 Type or print name Susan Henpin Telephone No. 505-748-1471 (This space for State use) TITLE Juil upper DATE May 3, 2002 APPPROVED BY TITLE Juil upper DATE 9 2002	I hereby certify that the information above is true and complete to the	best of my know was	~ waa ~ ~	-	
Type or print name Susan Herpin Telephone No. 505-748-1471 (This space for State use) Image: State use in the state of the state			-		
(This space for State use) APPPROVED BY	SIGNATURE <u>Meten la promitie El</u>	ngineering Tech	nician_DATE_	<u>May 3, 2002</u>	
APPPROVED BY	Type or print name Susan Henpin	A. A.		No. 505-748-1471	
	(This space for State use)	101	J. A D		