	•			محد مد		n Approved. get Bureau No. 42–R142
29 1982	DEPARTMENT C	O STATESMY OIL OF THE INTERNET)D	NM-189	169	
), C. D.		AL SURVEY ESTA,	NM 88210	6. IF INDIA	N, ALLOTTE	E OR TRIBE NAME
ESIA SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)			7. UNIT AGREEMENT NAME			
1. oil well	gas well othe			- 6. 1 AKM OF	deral'-	
2. NAME O	F OPERATOR Oil Company			10. FIELD OF		NAME
3. ADDRESS	S OF OPERATOR	- All de suit alle alle de la contraction de la	72102	Wildca	t Hu	rechuran
904 Hightower Bldg., Okla. City, Okla. 73102 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 2310' FSL & 1880' FWL Sec. 11-5S-27			AREA Sec. 1	1-5S-27E		
AT TOP		k 1880' FWL Sec Same	2. 11–5S–27	Chave		13. STATE New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:			14. API NO. 15. ELEVATIONS (SHOW DF, KDB, AND W GR 3992.8'			
FRACTURE T SHOOT OR A REPAIR WELF PULL OR AL MULTIPLE CO CHANGE ZON	ACIDIZE			(NOTE: Repor	DF	CEIVF
	OMPLETE			J. J	0	ct 2 7 1982
ABANDON* (other) 17. DESCRIB including	OMPLETE	MPLETED OPERATION:	S (Clearly stat ork. If well is d zones pertiner	e all pertinent (MINER details, and ed. give 30	330.) CT 2 7 1982 OIL & GAS
ABANDON* (other) 17. DESCRIB including	DMPLETE	MPLETED OPERATION:	zones pertiner	e all pertinent (MINER details, and ed. give 30	330.) CT 2 7 1982 OIL & GAS
ABANDON* (other) 17. DESCRIB including measure	DMPLETE	MPLETED OPERATIONS arting any proposed wo this for all markers and	(Fusselma	e all pertinent of irectionally drill to this work.)* In Perfs 71	MINER details, and ed, give 433	OIL & GAS OIL & GAS ALS MGMT. SERVICE ALS MGMT. SERVICE DUMP
ABANDON* (other) 17. DESCRIB including measure 9-28-82	DMPLETE	MPLETED OPERATION arting any proposed wo this for all markers and ump and tubing. CIBP @ 7000'. top of BP. Pe	(Fusselmarforate St	e all pertinent of irectionally drill to this work.) to the perfs 71 trawn Zone,	MINER details, and ed, give 433	OIL & GAS OIL & GAS ALS MGMT. SERVICE ALS MGMT. SERVICE DUMP
ABANDON* (other) 17. DESCRIB including measures 9-28-82 9-29-82	DMPLETE	MPLETED OPERATION arting any proposed wo this for all markers and ump and tubing. CIBP @ 7000'. top of BP. Pe 6785'; 6830'-68	(Fusselmarforate St	e all pertinent of irectionally drill to this work.) to the perfs 71 trawn Zone,	MINER details, and ed, give 433	OIL & GAS OIL & GAS ALS MGMT. SERVICE ALS MGMT. SERVICE DUMP
ABANDON* (other) 17. DESCRIB including measures 9-28-82 9-29-82	DMPLETE	MPLETED OPERATION arting any proposed wo this for all markers and ump and tubing. CIBP @ 7000'. top of BP. Pe 6785'; 6830'-68	(Fusselmarforate St	e all pertinent of irectionally drill to this work.) to the perfs 71 trawn Zone,	MINER details, and ed, give 433	OIL & GAS OIL & GAS ALS MGMT. SERVICE ALS MGMT. SERVICE DUMP

18. I hereby contify that the foregoing is true and correct

ORIG. SGD.) DAVID R. GLASS CONDITIONS OF APPROVA 16 A2:8 1982

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO
See Instructions on Reverse Side