

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
Artesia, NM 88210

NM Oil Cons. Commission
STANDARD INSTRUCTIONS ON REVERSE SIDE

Form approved.
Budget Bureau No. 1004-011
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-16069

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Coyote Federal

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

Pecos Slope Abo

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 12-T8S-R24E

12. COUNTY OR PARISH 13. STATE

Chaves

NM

SUNDRY NOTICES AND REPORTS

(Do not use this form for proposals to drill or to deepen or plug back to a well or reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

McClellan Oil Corporation

3. ADDRESS OF OPERATOR

P.O. Drawer 730, Roswell, NM 88202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

1528' FSL & 660' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, HT, GR, etc.)

3598' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

X

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

6/20/87: TD at 3956'. Ran Schlumberger CNL-LDT-DLL.

6/21/87: Plugged and abandoned well as follows, as per verbal orders from Armando Lopez:

Set 35 sx plug from 3300' to 3400'. WOC - 1 hour. Tagged plug at 3278'.

Set 35 sx plug from 1300' to 1400'.

Set 35 sx plug from 825' to 925'. WOC - 1½ hours. Tagged plug at 810'.

Set 15 sx surface plug.

Will clean location & install dry hole marker after rig moves.

18. I hereby certify that the foregoing is true and correct

SIGNED Paul Ragdale

TITLE Operations Manager

DATE 7/24/87

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED
DATE
PETER W. CHESTER

JUL 28 1987

BUREAU OF LAND MANAGEMENT
ROSSELL RESOURCE AREA

*See Instructions on Reverse Side