

RECEIVED BY

JUN 10 1985

O. C. D.

ARTESIA OFFICE

UNITED STATES

DEPARTMENT OF THE INTERIOR (Other Instructions on re-
BUREAU OF LAND MANAGEMENT verse side)

NEW OIL CONS. COMMISSION

Drawer DD

Artesia, NM 88210

SUBMIT IN TRIPLICATE*

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

c/s F

5. LEASE DESIGNATION AND SERIAL NO.
NM-18821

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

(Do not use this form for proposals to drill or to deepen or plug back to
a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals.)

1. OIL GAS
WELL ☐ WELL ☐ OTHER ☒ DRY HOLE

7. UNIT AGREEMENT NAME

2. NAME OF OPERATOR
Read & Stevens, Inc.

8. FARM OR LEASE NAME
NORTH HAYSTACK FEDERAL

3. ADDRESS OF OPERATOR
P.O. Box 1518, Roswell, NM 88201

9. WELL NO.
3

4. LOCATION OF WELL (Report location clearly and in accordance with State
requirements.* See also space 17 below.)
At surface

10. FIELD AND POOL, OR WILDCAT
Wildcat Abo

660' FNL and 660' FWL

11. SEC. T., R., M., OR BLK. AND
SURVEY OR AREA
Sec. 34-5S-26E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3943' GR

12. COUNTY OR PARISH
Chaves

13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☒
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including
estimated date of starting any proposed work. If well is directionally drilled give subsurface locations and measured
and true vertical depths for all markers and zones pertinent to this work.)*

- 1) Notify Roswell BLM of plugging operations- 624-1790.
- 2) Circ hole w/salt gel mud.
- 3) Set CIBP @ 4400', dump 35' cmt on top of plug.
- 4) Spot 100', 25sx, Class "C" cmt, 2200' to 2100'.
- 5) Cut csg off @ 1500', spot 50sx stub plug, 100', 1450' to 1550'.
- 6) Spot 50sx Class "C" cmt, 1050'-1150', across 8 5/8" csg shoe, tag plug.
- 7) Spot 25sx Class "C" cmt from surface to 50'.
- 8) Level pits, clean loc, install dry hole marker, rip loc & road, re-seed.

*Verbal approval given by Peter Chester, Roswell BLM.

I hereby certify that the foregoing is true and correct

SIGNED

TITLE Drilling & Production Manager

DATE 6/4/85

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

APPROVED
PETER W. CHESTER

JUN 6 1985

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA



THE UNIVERSITY OF CHICAGO PRESS