

DISTRICT I
P.O. Box 1960, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-005-61710

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
LG-0442

7. Lease Name or Unit Agreement Name
Amoco State

8. Well No.
#1

9. Pool name or Wildcat
Palma Mesa

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3929 GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
Hanson Operating Company, Inc.

3. Address of Operator
P.O. Box 1515, Roswell, NM 88202-1515

4. Well Location
Unit Letter G : 1980 Feet From The North Line and 1980 Feet From The East Line
Section 23 Township 8S Range 27E NMPM Chaves County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Hanson Operating Company, Inc. plans to plug & abandon the above well in the following manner: Perforate 4 1/2" casing @ 50'.
Spot 10 sxs cement surface plug. Circ. cut to surface.
Spot 100' cement plug at 1435'-1335' and tag. Inside + outside 4 1/2" casing. Tag.
Spot 25 sxs cement plug at 2740'-2640'. Perforate 4 1/2" casing @ 2240'. Squeeze 100' cement Plug inside + out.
Spot 100' cement plug at 50', inside and outside 4 1/2" casing. Side 4 1/2" casing. Tag.
Freeport cut & pull 4 1/2" casing.
Spot 25 sxs cement plug at 4960'.
Spot 25 sxs cement plug at 6000'-5900'.
Run & set CIBP at 6204' with 35 sxs cement on top of CIBP.
Circulate brine gel to surface.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Betsy Speer TITLE Prod. Analyst DATE 2-15-01
 TYPE OR PRINT NAME Betsy Speer TELEPHONE NO. 505-622-7330

(This space for State Use)

APPROVED BY Mae Stillfield TITLE Field Rep. II DATE 2/22/2001
 CONDITIONS OF APPROVAL, IF ANY: