

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	RECEIVED BY DEC 27 1984 O. C. D.	6. LEASE DESIGNATION AND SERIAL NO. NM 27634
2. NAME OF OPERATOR Stevens Operating Corporation	ARTESIA, OFFICE	7. UNIT AGREEMENT NAME N/A
3. ADDRESS OF OPERATOR P. O. Box 2203 Roswell, New Mexico 88201		8. FARM OR LEASE NAME Hanagan Federal
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 330 FNL, 2310 FEL, Sec. 23, T-7-S, R-26-E		9. WELL NO. 3
14. PERMIT NO.	15. ELEVATIONS (Show whether of, RT, or, etc.) 3803 GR	10. FIELD AND POOL, OR WILDCAT Wildcat - San Andres
		11. SEC., T., R., M., OR BLM, AND SURVEY OR AREA Sec. 23, T-7-S, R-26-E
		12. COUNTY OR PARISH Chaves
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	☐	WATER SHUT-OFF	☐
FRACURE TREAT	☐	FRACURE TREATMENT	☐
SHOOT OR ACIDIZE	☐	SHOOTING OR ACIDIZING	☐
REPAIR WELL	☐	(Other)	☐
(Other)	☐		
PLUG OR ALTER CASING	☐	REPAIRING WELL	☐
MULTIPLE COMPLETION	☐	ALTERING CASING	☐
ABANDON*	☒	ABANDONMENT*	☐
CHANGE PLANS	☐		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

8 5/8" surface csg @ 302' cement circ. 4 1/2" Production csg @ 1630'.
Approximate TOC @ 825'. San Andres Perforations: 1450 1/2'-1475'.

P & A Proposal:

1. Set CIBP @ 1410' + 35' cement cap.
2. Find Free Point of 4 1/2 casing.
3. Perforate 4 1/2 casing @ 650'. Pump to circ cement to surface outside 4 1/2 casing and will leave cement inside 4 1/2 casing to surface.
4. Set dry hole marker.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Production Controller DATE 12-13-84

(This space for Federal or State Approval)

APPROVED [Signature] TITLE PETER W. CHESTER DATE

CONDITIONS OF APPROVAL, IF ANY:

DEC 27 1984

*See Instructions on Reverse Side