

NM OIL CONS. COMMISSION
Drawer DD
Artesia, NM 881

Form 3160-5
(November 1983)
(Formerly 9-331)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. NAME OF OPERATOR
Stevens Operating Corporation
3. ADDRESS OF OPERATOR
P. O. Box 2203 Roswell, NM 88201
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

RECEIVED BY

MAR 05 1986

O. C. D.

330 FNL, 2310 FEL, Sec. 23, T-7-S, R-26-E

14. PERMIT NO.
15. ELEVATIONS (Show whether of, ft, or, etc.)
3803 GR

6. LEASE DESIGNATION AND SERIAL NO.

NM 27634

8. IF INDIAN, ALLOTTEE OR TRIBE NAME

N/A

7. UNIT AGREEMENT NAME

N/A

8. FARM OR LEASE NAME

Hanagan Federal

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 23, T-7-S, R-26-E

12. COUNTY OR PARISH 13. STATE

Chaves

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACURE TREAT

SHOOT OR ACIDIZING

REPAIR WELL

(Other)

PCLL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1-2-85

1. Set CIBP @ 1410' + 35' cement cap.

2. Find Free Point fo 4 1/2 csg @ 650'.

3. Perforate 4 1/2 csg @ 650'. Pump 340 sxs class "C" w/2% CaCl₂ to circ cmnt to surface outside 4 1/2 csg and leave cement inside 4 1/2 csg to surface.

4. Set Dry Hole Marker.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Production Controller

DATE 1-3-85

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL

MAR 3 1986

*See Instructions on Reverse Side

BUREAU OF LAND MANAGEMENT
WELL RESOURCE AREA

Note: IS U.S.C. Section 1000, who shall be liable for any person knowingly and willfully to make to any department or agency of the

Post ID-2
2-8-85
PYA

