
	ci
Submit 3 Copies To Appropriate Lastrict State of New Mexic	co Form C-103
Office Energy Minerals and Natural	191 /
District I Lifetgy, Witherland and Waterland 1625 i French Dr., Hobbs, NM 83240	WELL API NO.
District II OH CONSERVATION D	IVISION 30005-61735
811 South First, Artesia, NM 88210 District III 2040 South Pachec	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 8750	
2040 South Pacheco, Santa Fe, NM 87505	6. State Off & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR FROPOSALS TO DRILL OR TO DEEPEN OR PLUG DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR	
PROPOSALS.)	Twin Lakes San Andres Unit
1. Type of Well:)
Oil Well Gas Well Other Injection 2. Name of Operator	7. Well No.
Concho Oil & Gas Corp.	116
3. Address of Operator	8. Pool name or Wildcat
110 W. Louisiana Ste 410; Midland, Tx 79701	Twin Lakes; San Andres (Assoc)
4. Well Location	
Unit Letter D: 330 Feet from the NORTH line and 330 feet from the WEST line	
Section 18 Township 9S Range 29	
10. Elevation (Show whether DR, 13974 GR	KKB, R1, GR, etc.)
11. Check Appropriate Box to Indicate Natu	re of Notice, Report or Other Data
NOTICE OF INTENTION TO: \ /	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK 🗀 PLUG AND ABANDON 🗡 📗 F	REMEDIAL WORK ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS. PLUG AND
	ABANDONMENT
	CASING TEST AND CEMENT JOB
<u> </u>	OTHER:
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion	
or recompilation.	
of feeding nation.	
Concho Oil & Gas Corp. respectfully request approval to plug & abandon the Twin Lakes San Andres	
Unit No. 116 according to the following procedure:Notify NMOCD Artesia 24 hrs prior to commencemer	at of procedure
 Notify NMOCD Artesia 24 hrs prior to commencemer Set 190, plug @ 2590-2690. 	118 19 20 2122
3. Circ hole w/ mud.	13.60° (12.50°)
4. Set 100' plug @ 2000-2100'.	T
5. Set 100' plug @ 1590-1690'.	P OCT POIL S
6. Cut csg @ 940' & POOH.	RECEIVED 81
7. Set 100' cmt plug @ 890-990'. WOC & tag.	OCD - ARTESIA
8. Circ cmt from 263' to surface.9. Cut off wellhead & install dry hole marker.	
9. Out on Weillead & Install dry hole marker.	The second
1	
I hereby certify that the information above is true and complete to the best	st of my knowledge and belief.
SIGNATURE TITLE	Production Analyst DATE 10-18-01
SIGNATURE TITLE	110taction Analyst DIVID 10-10-01
Type or print name Terri Stathem Telephone 10/915/683-7443	
(This space for State use)	Tield Sen 10 10 20 11
APPPROVED BY TITLE	DATE/0-390)
Conditions of approval, if any:	<u> </u>

TLSAU #116





Original Perf Details: P1: 2698, 99, 2700, 01, 02, 03, 04, 05, 14

6000 gals 20% acid

Apr-88 Add P1: 2710, 11, 13, 17, 18, 19, 20, 27, 28, 29, 30, 31, 32, 36, 37, 38

No treatment