	, <del>-</del>	\c_1	f-	
Submit 3 Copies To Appropriate District	State of New Mex	$\mathcal{C}^{\prime}$	Form C-103	
Office District I	Energy, Minerals and Natur	ral Resources	Revised March 25, 1999	
1625 N. French Dr., Hobbs, NM 88240		<b>\</b>	WELL API NO. 30-005-62635	
District II 811 South First, Artesia, NM 88210	rst, Artesia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type of Lease	
District III 1000 Rio Brazos Rd., Aztec, NM 87410	2040 South Pach	Į.	STATE □ FEE □xx	
District IV	Santa Fe, NM 87	(505	6. State Oil & Gas Lease No.	
2040 South Pacheco, Santa Fe, NM 87505			C. J. N	
SUNDRY NOTICE (DO NOT USE THIS FORM FOR PROPOSAL DIFFERENT RESERVOIR. USE "APPLICAT PROPOSALS.)  1. Type of Well: Oil Well	TION FOR PERMIT" (FORM C-101) FO	JG BACK TO A	7. Lease Name or Unit Agreement Name: LE 6	
2. Name of Operator			8. Well No. 1	
Jalapeno Corporation			9. Pool name or Wildcat	
3. Address of Operator P. O. Box 1608 Alburquerque, New	v Mexico 87103-1608		Racetrack San Andres	
4. Well Location				
Unit Letter_O 330	feet from the South line	and 2310 fe		
Section 6	Township 10S Ra	nge 28E	NMPM Chaves County	
	10. Elevation (Show whether Dia 3824.5 GR.	R, RKB, RT, GR, etc	c.)	
	propriate Box to Indicate N	ature of Notice,	Report or Other Data	
NOTICE OF INT	ENTION TO:	SUB REMEDIAL WOR	SEQUENT REPORT OF:	
	CHANGE PLANS	COMMENCE DRI	ILLING OPNS. PLUG AND	
	MULTIPLE  COMPLETION	CASING TEST AI	ABANDONMENT	
OTHER:	COMPLETION	OTHER:		
12 Describe proposed or completed	operations. (Clearly state all pe	rtinent details, and g	give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion				
or recompilation.	+ 255x cement Plug 2187-2	ogn. TAG or CIB	3Pw/35 cents T D 2187	
1) Set 25 sack plug from 1615' to 1695' to cover top of San Andres and tag.				
<ul><li>2) Fill hole with mud and cut casing.</li><li>3) Set 35 sack plug across casing stub and tag.</li></ul>				
	4) Set 35 sack plug from 1000' to 1100' to cover top of Queen.			
5) Set 35 sack plug from 215' to 315' to cover base of surface casing. TAG				
6	Set ten sack plug at surface a	nd set dry hole mark	ker. जूर्ड अवस्थाने के	
			<i>ं %्</i> र्	
			Soft B	
I hereby certify that the information	above is true and complete to the	best of my knowled	dge and belief.	
SIGNATURE). Cr. Hus	tamante TITLE	Production Supervis	sor DATE Feb.7,2000	
Type or print name J. A. Gustaman	tes		Telephone No. 505-347-2375	
(This space for State use)				
APPPROVED BY Mac S hall Conditions of approval, if any:	full TITLE	Field Rep. II	DATE 2/24/2300	

\* Notifie Nmoch to witness Plugging Operations