

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-005-62769

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
V-4507

7. Lease Name or Unit Agreement Name
Samedan ATH State

8. Well No.
1

9. Pool name or Wildcat
Four Ranch Wolfcamp, South

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3673.3' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. Name of Operator
YATES PETROLEUM CORPORATION

3. Address of Operator
105 South 4th St., Artesia, NM 88210

4. Well Location
Unit Letter I : 1980 Feet From The South Line and 660 Feet From The East Line
Section 35 Township 10S Range 26E NMMPM Chaves County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3673.3' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug & abandon as follows:

- Load casing with 2% KCL water. Nipple down wellhead and nipple up BOP.
- RIH with tubing to 3684'. Circulate hole with 10 ppg plugging mud.
- Spot a 30 sack Class C cement plug from 3684-3384'. TAG 3581 SET 3296' TAG
- POOH with tubing to 2000'. Spot a 30 sack Class C cement plug from 2000-1700'. Inside + Outside
- POOH with tubing to 1300'. Spot a 30 sack Class C cement plug at the base of the 8-5/8" casing from 1300-1000'. Inside + Outside 5 1/2" csg. TAG
- Spot a 10 sack Class C cement plug at surface. Perforate 5 1/2" csg. 30'. Circ. cnt to surface.
- Install regulation abandonment marker.

NOTE: Top of cement is at 3720'. Casing is bad at 3656' and cannot get tools past 3684'. There is a RBP set at 4750' (which is underneath the bad casing).

NOTIFY OCD-ARTESIA (505-748-1283) 24 HOURS PRIOR TO COMMENCING PLUGGING OPERATIONS

*Notify N.M.O.C.D. to witness Plugging Operations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Operations Technician DATE April 27, 2001

TYPE OR PRINT NAME Rusty Klein

TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY Mike Stillfield TITLE Envir. Eng. Spc. I DATE 5/4/2001

CONDITIONS OF APPROVAL, IF ANY: