

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-005-63117
Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
State Oil & Gas Lease No. VA - 1234
Lease Name or Unit Agreement Name Katie Elder
Well No. 2
Pool name or Wildcat Chisum, San Andres; South

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	
Name of Operator Marbob Energy Corporation	
Address of Operator P.O. Box 227, Artesia, N M 88210	
Well Location Unit Letter <u>G</u> : <u>2270</u> Feet From The <u>North</u> Line and <u>2200</u> Feet From The <u>East</u> Line Section <u>36</u> Township <u>11S</u> Range <u>27E</u> NMPM <u>Chaves</u> County	
Elevation (Show whether DF, RKB, RT, GR, etc.) 3742' GR	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Notify OCD 24 Hrs. before start
2. RIH tag CIBP @ 2630 circulate well w/ 9.8# mud
3. Spot 100' cmt. plug 12630
4. Cut & pull 5 1/2 casing @ 2000' + or -
5. RIH spot 100' cmt. plug 50' in & out cut woc & tag
6. POH to 1450 spot 100' cmt. plug 255x cement Plug 1500 1400
7. POH to 910' spot 100' cmt plug 255x cement Plug 960 860
8. POH to 310 spot 100' cmt. plug woc & tag (8 5/8 shoe 260')
9. POH to 60' circulate cmt to surface
10. cut off well head install dry hole marker



* Notify NMOC to witness Plugging Operations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Wayne Brooks TITLE agent DATE 01-03-2000

TYPE OR PRINT NAME Wayne Brooks TELEPHONE NO. 915-6848890

(This space for State Use)

APPROVED BY Mike Stubblefield TITLE Field Rep. II DATE 1/4/2000

CONDITIONS OF APPROVAL, IF ANY: