

CISF
JP

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-005-63169
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Hanlad State
8. Well No. #14
9. Pool name or Wildcat Diablo San Andres
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3808GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Hanson Operating Company, Inc.
3. Address of Operator P.O. Box 1515, Roswell, NM 88202-1515
4. Well Location Unit Letter B : 330 Feet From The North Line and 2230 Feet From The West Line Section 28 Township 10S Range 27E NMPM Chaves County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Hanson Operating Company, Inc. plans to plug & abandon the above well in the following manner:

10 sxs cement surface plug.
Spot 25 sxs cement plug at 550'-450' and tag.
Spot 25 sxs cement plug at 1032'-932' and tag.
Circulate brine gel to surface.
Run and set CIBP at 2454'-2354' with 35 sxs cement.

RECEIVED
OCD ARTESIA

X Notify N.M.O.C.D. to witness Plugging Operations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Betsy Speer TITLE Prod. Analyst DATE 2-14-01
505-622-7330
TELEPHONE NO.

TYPE OR PRINT NAME Betsy Speer

(This space for State Use)

APPROVED BY Mrs. J. Stullfield TITLE Field Rep. II DATE 2/20/2001
CONDITIONS OF APPROVAL, IF ANY: