Submit 3 Copies To Appropriate District State of New M		2151	
State of frew in	Mexico	· CO	Form C-103
Office Energy, Minerals and Na		l all	Revised March 25, 1999
District I 1625 N. French Dr., Hobbs, NM 88240	.carar x cooo ar coo	WELL API NO.	
District II OU CONSERVATIO	N DIVISION	30-005-63238	
Ell South First, Artesia. NM 88210 District III 1220 South St. F1		5. Indicate Type of Lease STATE FEE X	
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe. NM		6. State Oil & Gas Lease No.	
District IV 1220 S. St. Francis Dr., Santa Fe, NM		0. State Off & Of	is Ecase 110.
87505 SUNDRY NOTICES AND REPORTS ON WEL		7 Lease Name or	Unit Agreement Name:
(DO NOT LISE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR	PLUG BACK TO A		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101)	FOR SUCH	Fred ASY Com	
PROPOSALS.) 1. Type of Well:			
Oil Well Gas Well Other X Dry hole			
2. Name of Operator		7. Well No.	
Yates Petroleum Corporation		#1 8. Pool name or	Wildcat
3. Address of Operator		Pecos Slope Abo	
105 S. 4th Street Artesia, NM 88210		Fecos slope Abo	
4. Well Location		// 	
		.′	
Unit Letter <u>B: 700</u> feet from the North	line and 1980	feet from the E	ast line
Section 12 Township 5S Range		MPM Chaves	County
10. Elevation (Show whether	DR, KKB, K1, GK, ei 85' GR	<i>c.)</i>	
11. Check Appropriate Box to Indicate		Report or Other 1	Data
NOTICE OF INTENTION TO:	SUF	SEQUENT REI	PORT OF:
			ALTERING
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WOR		CASING
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DR	IILLING OPNS. 🔲	PLUG AND ABANDONMENT X
MUTIPLE	CASING TEST A	ND	
PULL OR ALTER CASING COMPLETION	CEMENT JOB	[]	}
	OTHER:		
OTHER:	OTHER:	nertinent dates, incli	uding estimated date of
OTHER: Describe proposed or completed operations. (Clearly state all pert	inent details, and give	pertinent dates, included	ading estimated date of osed completion or
OTHER: Describe proposed or completed operations. (Clearly state all pert starting any proposed work). SEE RULE 1103. For Multiple Com-	inent details, and give	pertinent dates, included bore diagram of prop	uding estimated date of losed completion or
OTHER: Describe proposed or completed operations. (Clearly state all pert starting any proposed work). SEE RULE 1103. For Multiple Comrecompilation. 2/2/01 – Reached TD at 4100° at 3:30 AM.	inent details, and give	pertinent dates, included bore diagram of prop	ading estimated date of osed completion or
OTHER: Describe proposed or completed operations. (Clearly state all pert starting any proposed work). SEE RULE 1103. For Multiple Comrecompilation. 2/2/01 – Reached TD at 4100' at 3:30 AM. Ran open hole logs. Loggers' TD 4099'.	inent details, and give pletions: Attach well	pertinent dates, included bore diagram of prop	uding estimated date of osed completion or
OTHER: Describe proposed or completed operations. (Clearly state all pert starting any proposed work). SEE RULE 1103. For Multiple Comrecompilation. 2/2/01 - Reached TD at 4100' at 3:30 AM. Ran open hole logs. Loggers' TD 4099'. Received plugging instructions. Notified Phil Hawkins with	inent details, and give pletions: Attach well	pertinent dates, included bore diagram of prop	ading estimated date of osed completion or
OTHER: Describe proposed or completed operations. (Clearly state all pert starting any proposed work). SEE RULE 1103. For Multiple Comrecompilation. 2/2/01 - Reached TD at 4100' at 3:30 AM. Ran open hole logs. Loggers' TD 4099'. Received plugging instructions. Notified Phil Hawkins with 2/3/01 - Set cement plugs as follows:	inent details, and give pletions: Attach well	pertinent dates, inclubore diagram of prop	uding estimated date of posed completion or
OTHER: Describe proposed or completed operations. (Clearly state all pert starting any proposed work). SEE RULE 1103. For Multiple Conrecompilation. 2/2/01 - Reached TD at 4100' at 3:30 AM. Ran open hole logs. Loggers' TD 4099'. Received plugging instructions. Notified Phil Hawkins with 2/3/01 - Set cement plugs as follows: 4025' - 30 sxs C neat 3005' - 30	inent details, and give pletions: Attach well th OCD.	pertinent dates, included bore diagram of prop	osed completion of
OTHER: Describe proposed or completed operations. (Clearly state all pert starting any proposed work). SEE RULE 1103. For Multiple Comrecompilation. 2/2/01 - Reached TD at 4100' at 3:30 AM. Ran open hole logs. Loggers' TD 4099'. Received plugging instructions. Notified Phil Hawkins with 2/3/01 - Set cement plugs as follows: 4025' - 30 sxs C neat 3005' - 30 1655' - 30 sxs C neat 1530' - 30 1530' - 30	inent details, and give pletions: Attach well th OCD. sxs C neat sxs C neat	bore diagram of prop	osed completion of
OTHER: Describe proposed or completed operations. (Clearly state all pert starting any proposed work). SEE RULE 1103. For Multiple Comrecompilation. 2/2/01 - Reached TD at 4100' at 3:30 AM. Ran open hole logs. Loggers' TD 4099'. Received plugging instructions. Notified Phil Hawkins with 2/3/01 - Set cement plugs as follows: 4025' - 30 sxs C neat 3005' - 30 1655' - 30 sxs C neat 1530' - 30 950' - 60 sxs C + 3% CaCl2. TIH and tagged cement at 841'. Set surface plug 20 sxs	inent details, and give pletions: Attach well th OCD. sxs C neat sxs C neat	bore diagram of prop	osed completion of
OTHER: Describe proposed or completed operations. (Clearly state all pert starting any proposed work). SEE RULE 1103. For Multiple Comrecompilation. 2/2/01 - Reached TD at 4100' at 3:30 AM. Ran open hole logs. Loggers' TD 4099'. Received plugging instructions. Notified Phil Hawkins with 2/3/01 - Set cement plugs as follows: 4025' - 30 sxs C neat 3005' - 30 1655' - 30 sxs C neat 1530' - 30	inent details, and give pletions: Attach well th OCD. sxs C neat sxs C neat	bore diagram of prop	osed completion of
OTHER: Describe proposed or completed operations. (Clearly state all pert starting any proposed work). SEE RULE 1103. For Multiple Comrecompilation. 2/2/01 - Reached TD at 4100' at 3:30 AM. Ran open hole logs. Loggers' TD 4099'. Received plugging instructions. Notified Phil Hawkins with 2/3/01 - Set cement plugs as follows: 4025' - 30 sxs C neat 3005' - 30 1655' - 30 sxs C neat 1530' - 30 950' - 60 sxs C + 3% CaCl2. TIH and tagged cement at 841'. Set surface plug 20 sxs	inent details, and give pletions: Attach well th OCD. sxs C neat sxs C neat	bore diagram of prop	ading estimated date of bosed completion or
OTHER: Describe proposed or completed operations. (Clearly state all pert starting any proposed work). SEE RULE 1103. For Multiple Comrecompilation. 2/2/01 - Reached TD at 4100' at 3:30 AM. Ran open hole logs. Loggers' TD 4099'. Received plugging instructions. Notified Phil Hawkins with 2/3/01 - Set cement plugs as follows: 4025' - 30 sxs C neat 3005' - 30 start 1530' - 30	inent details, and give pletions: Attach well th OCD. sxs C neat sxs C neat Company C	set at 7:00 PM.	osed completion of
OTHER: Describe proposed or completed operations. (Clearly state all pert starting any proposed work). SEE RULE 1103. For Multiple Comrecompilation. 2/2/01 - Reached TD at 4100' at 3:30 AM. Ran open hole logs. Loggers' TD 4099'. Received plugging instructions. Notified Phil Hawkins with 2/3/01 - Set cement plugs as follows: 4025' - 30 sxs C neat 3005' - 30 1655' - 30 sxs C neat 1530' - 30	inent details, and give pletions: Attach well th OCD. sxs C neat sxs C neat C neat. Last plug the best of my knowle	set at 7:00 PM.	Poct Put
OTHER: Describe proposed or completed operations. (Clearly state all pert starting any proposed work). SEE RULE 1103. For Multiple Comrecompilation. 2/2/01 - Reached TD at 4100' at 3:30 AM. Ran open hole logs. Loggers' TD 4099'. Received plugging instructions. Notified Phil Hawkins with 2/3/01 - Set cement plugs as follows: 4025' - 30 sxs C neat 3005' - 30 start 1530' - 30	inent details, and give pletions: Attach well th OCD. sxs C neat sxs C neat C neat. Last plug the best of my knowle	set at 7:00 PM.	Poct Put
OTHER: Describe proposed or completed operations. (Clearly state all pert starting any proposed work). SEE RULE 1103. For Multiple Confections are compilation. 2/2/01 - Reached TD at 4100' at 3:30 AM. Ran open hole logs. Loggers' TD 4099'. Received plugging instructions. Notified Phil Hawkins with 2/3/01 - Set cement plugs as follows: 4025' - 30 sxs C neat 3005' - 30 1655' - 30 sxs C neat 1530' - 30	inent details, and give pletions: Attach well th OCD. sxs C neat sxs C neat C neat. Last plug the best of my knowle	set at 7:00 PM. Edge and belief.	January 21, 2002
Describe proposed or completed operations. (Clearly state all pert starting any proposed work). SEE RULE 1103. For Multiple Comrecompilation. 2/2/01 - Reached TD at 4100' at 3:30 AM. Ran open hole logs. Loggers' TD 4099'. Received plugging instructions. Notified Phil Hawkins with 2/3/01 - Set cement plugs as follows: 4025' - 30 sxs C neat 3005' - 30 states 1530' - 3	inent details, and give pletions: Attach well th OCD. sxs C neat sxs C neat C neat. Last plug the best of my knowle	set at 7:00 PM. Edge and belief.	Poct Put
OTHER: Describe proposed or completed operations. (Clearly state all pert starting any proposed work). SEE RULE 1103. For Multiple Confections. 2/2/01 - Reached TD at 4100' at 3:30 AM. Ran open hole logs. Loggers' TD 4099'. Received plugging instructions. Notified Phil Hawkins with 2/3/01 - Set cement plugs as follows: 4025' - 30 sxs C neat 3005' - 30 1655' - 30 sxs C neat 1530' - 30 1530	inent details, and give pletions: Attach well th OCD. sxs C neat sxs C neat C neat. Last plug the best of my knowle	set at 7:00 PM. Edge and belief.	January 21, 2002
Describe proposed or completed operations. (Clearly state all pert starting any proposed work). SEE RULE 1103. For Multiple Comrecompilation. 2/2/01 - Reached TD at 4100' at 3:30 AM. Ran open hole logs. Loggers' TD 4099'. Received plugging instructions. Notified Phil Hawkins with 2/3/01 - Set cement plugs as follows: 4025' - 30 sxs C neat 3005' - 30 states 1530' - 3	inent details, and give pletions: Attach well th OCD. sxs C neat sxs C neat C neat. Last plug the best of my knowle	set at 7:00 PM. Edge and belief.	January 21, 2002