			CISE	<i>,</i>
Submit 3 Copies To Appropriate District Office District I State of New Mexico Energy, Minerals and Natural Resources			Form C-103 Revised March 25, 1999	
1625 N. French Dr., Hobbs, NM 88240 District II			WELL API NO.	
811 South First, Artesia, NM 88210 OIL CONSERVATION DIVISION		30-005-63298		
District III 1000 Rio Brazos Rd., Aztec, NM 87410 1220 South St. Francis Dr.		5. Indicate Type STATE	of Lease X FEE	
District IV Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM		6. State Oil & C		
87505		VO-5523		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C. WIL) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well X Gas Well Other			7. Lease Name or Unit Agreement Name: Vista AVS State	
2. Name of Operator		2002 3	7. Well No.	
Yates Petroleum Corpo		CEIVED &	#5	
3. Address of Operator	• *	- ARTESIA 👸	8. Pool name or	
105 S. 4th Street Artesia, NM 88210		Wildcat San Andres		
4. Well Location		207 67 66 /	<u> </u>	
Unit Letter <u>A: 33</u> Section 21	feet from the North Township 98 Range	26E NN	MPM Chave	_
	10. Elevation (Show whether I		c.)	
11 Charle A		0' GR		
NOTICE OF IN	ppropriate Box to Indicate N			
	T	SUB	SEQUENT REI	
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WOR		ALTERING CASING PLUG AND
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AI	ILLING OPNS. X	ABANDONMENT
OTHER:		OTHER:		
Describe proposed or completed opstarting any proposed work). SEE Frecompilation. 10/28/00 – Spud 20" hole at 10 11/6/00 – Resumed drilling with 11/9/00 – Reached TD of surfor Ran 22 joints (935.73') 8-5/8" 2 set at 889.48'. Cemented with with 200 sxs C with 2% \$1 (yld 11/10/00 -PD at 2:15 AM. Bum Drilled out at 10:00 PM. WOC	CULE 1103. For Multiple Compl D:00 AM. Set 40' of 16" cond h 12-1/4" hole with rotary to lice hole at 935' at 6:45 PM. 14# J55 casing, landed at 93 h 350 sxs 35:65 Poz C with 6% 1.32, wt 14.8). Inped plug to 600 psi, held Ol	etions: Attach wellb ductor pipe, cem- ol at 2:30 PM. '2'. Texas pattern 5 D20 + 2% \$1 + 1/4 K. Circ 61 sxs WO	ore diagram of propented to surface. guide shoe set copps D29 (yld 1.99)	osed completion or at 932'. Insert float P, wt 12.6). Tailed in
Hereby certify that the information SIGNATURE Susan Hereby Crype or print name Susan Hereby Crype or State use ORIG	pin BINAL SIGNED BY TIM W QU	ngineering Tech	nnician DATE_	No. 505-748-1471
APPPROVED BY Conditions of approval, if any:	RICT II SUPERVISOR TITLE			