orfin 9-331 a (Feb. 1951)		IIA G G G (SUBMIT IN TRIPLICATE)
x	£1.4 - 5	UNITED STATES

		e 4	1.7	911	'n
Bue Ap j	dget Bureau i proval expires	No. 42 - 12-31-	R368.4. 60.		
Land Office	NM He 02	8			
Lease Ivo.		 -			

GPO 862040

NOTICE OF INTE NOTICE OF INTE NOTICE OF INTE	NTION TO CHANGE PLAP NTION TO TEST WATER NTION TO RE-DRILL OR NTION TO SHOOT OR A NTION TO PULL OR ALT NTION TO ABANDON WE	SHUT-OFF REPAIR WELL CIDIZE ER CASING	SUBSEQUENT REPORE SUBSEQUENT REPORE SUPPLEMENTARY W	7070	REPAIR.	X
NE/4 NW, (% 800. as Wildca	is located /4 Sec. 20	T2N R (Twp.) DeBaca	n. N line and 19 (Range) New Me	80 ft. from \(\frac{\fin}}}{\fint}}}}}}{\frac{\fin}}}}}}}{\frac{\f{\fir}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\fra	line of sec	•
•	•	loor above sea le	evel is 4888DFt.			
itate names of a	nd expected depths to o	Liceira condes abow e	AILS OF WORK izes, weights, and lengths of other important proposed	of proposed casings; ir work)	idicate mudding jobs	, cornent-
Spudded 3	/13/59 Comp s follows: 50' plug @ 50' plug s	bjective sands; show a ing points, and all and P&A 4/25, 5000° at 2500° at top of sur	izes, weights, and lengths of other important proposed	of proposed casings; ir work)		
Spudded 3 Plugged a When pit Roswell	/13/59 Comp. s follows: 50' plug 6 50' plug s 50' plug s Marker set	and P&A 4/25, 5000°, t 2500°, t top of sur	izes, weights, and lengths of other important proposed	led, notice	will be sent	1968 to