201110110	NO HENDAMON	I I Y	RS	R I · E R	Name ROY E. JOHNSON Time of Departure 7:00 AM	Date 1-30-86 Time of Return		
				H O U R S	In the space below indicate the performed, listing wells of least Signature Toj Confirmed	purpose of the trip an ses visited and any act	RECEIVED and the duties tion taken. SEP -7'89	
0	0 0	0 0	1 1	0 2	To state labs in Albuquerque to drop off water samples O.C. U. To N.M.B.M. in Socorro to drop off logs, 105's, to petrolegically Give J. Bailey tour of Bureau of Mines			
0	0	P	1	0	33-14S-1W (several wells) check on operations of geothermal wells within T or C city limits - OK			
0	0	0	2	0	To E.P.N.G. compressor station to check discharge pit and recomendations			
С	0	D	1	0	on reclaimation with J. Bailey J-7-25S-19W (lwell) check on plugging cleanup of deep geothermal well test			
0	0	P	7	0	Surface owner requests that pit not be filled in as will be used for water storage in discharge of geothermal water - OK (Amax Eplr.) 6,7, & 18T, 25S, R19W, 1,12, & 13 T25S R20W (numberous well) check and sample geothermal wells, Fresh water supply wells and local irrigation wells. Inspect geothermal greenhouse operations, consult with operator on disposal, and take water samples in a E-W and NE-SW orientians - facility OK (Burgett, Beall, McCants_L-10-33S-20W (lwell) check on P&A well location, pits filled in but not contoured with local surroundings, dry hole marker OK, will contact			
С	0	D	2	2				
0	.0	G 0	2 4	0	District II on findings (ARCO) N.M.S.U. geothermal operations, J. Bailey tour- OK New Mexico Tech library to research geothermal reservoir data with respect to discharge plans and hydrology.			
ں.۔	0	x	39		off duty and drive time.			
					•	٠.		
						•		
					•	•	•	
					1123			
						Per Diem UIC	Hours UIC	
					_	RFA	RFA	
					Other 983	Other 109.00	Other 61.00	
	TYPE INSPECTION PERFORMED				INSPECTION CLASSIFICATION			
H = MouseProping P = Plusting C = Plusting T = Artific = Proping P = Purchase H = Purchase H = Purchase				î	related to innection project to sulting from injection int injection well tosts, surface injection equ	 U = Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SHU, Indry injection and production wells, Water flows or pressure tests, surface injection equipment, plugging, etc.) 2 Inspections relating to Reclamation Fund Activity 		
ÿ 3	w • Garito III on the switch S • Cores				O * Ciner - Inspections not related Ferlamation Fund	3 = Ciner - Inspections not related to injection or Tre- Replacation Fund		
					E = indicates sume form of unfor field (show immediately below)	E = indicates some form of unforcement action makes to the field (show immediately below the letter U, R at 1)		

E = indicates some form of unforcement action rakes ... U.e. field (show immediately below the letter U. R. at 1)