September 24, 1970

Bryce Duggar P. O. Box 165 Carrizozo, New Mexico

Re: Edna Gallager Well
No.1-M, Sec. 26-6S-10E,
Lincoln County, New Mexico

Dear Mr. Duggar:

On September 22, 1970, an inspection was made of the site of the subject dry hole. Said inspection revealed there to be some wire and a small amount of other junk on the location. Before the plugging report may be approved the junk must be removed. In the alternative a statement from the landowner approving the condition of the well site may be obtained and submitted.

Further, the plugging report submitted on Form C-103, is not clear in one respect. It appears that more 8 5/8" casing was pulled than run and it is not clear how much casing was left in the hole. Please reveiw this part of the report and advise us of any correction. Also, please submit one copy of the electric log run on the well. This is required by Commission Rules & Regulations.

If there are any questions on these matters, do not hesitate to call upon me.

Very truly yours,

OIL CONSERVATION COMMISSION

R. L. Stamets

RLS: jw