

Burro Canyon Unit #1

2030' FSL & 2100' FEL of Section 2, T-21s, R-20-E,  
Otero County, New Mexico

Date	T.D.	
6/3/78	1175'	T. D. 1175' Lime. Shut down because Penasco River washed out county road.
6/4/78	1195'	Drlg. 1195' (21' in 8 hrs) Lime. (DSS 152)
6/5/78	1210'	Drlg. 1210' (15' in 8 hrs) Lime. (DSS 153)
6/6/78	1231'	Drlg. 1231' (21' in 8 hrs) Lime. (DSS 154).
6/7/78	1246'	Drlg. 1246' (15' in 8 hrs) Lime. (DSS 155).
6/8/78	1246'	Drlg. 1246' (0' in 8 hrs) Lime. Encountered junk in hole at 425' pushed to 935' could be portion of 13 3/8" csg. (DSS 156).
6/9/78	1246'	Drlg. 1246' (0' in 8 hrs) Lime. Drilled and bailed to 935' lost bailer in hole at that point. Will fish for bailer today and resume drilling. (DSS 157).
6/10/78	1246'	Drlg. 1246' (0' in 8 hrs) Lime. Recovered bailer and drilled 4 hours. Ran impression block and magnet, block did not show anything and there was no recovery from magnet. Will run wireline survey when bit is through fish.
6/11/78	1246'	Drlg. 1246' (0' in 8 hrs) Lime. 11" bailer will not go deeper than 935'. Now using 9" bailer and drilling at 938', drilled 3' of old hole.
6/12/78	1246'	Drlg. 1246' (0' in 8 hrs ) Lime. Drilled 7' in 8 hours. Now cleaning out at 945', bit size 12".
6/13/78	1246'	Drlg. 1246' (0' in 8 hrs) Lime. Drilled and bailed 120' to 1065'. Bailer hung up at 120' on trip out, confirming evidence that fish is bottom joint of casing.
6/14/78	1246'	Drlg. 1246' (0' in 8 hrs ) Lime. Drilled 5' to 1070'.
6/15/78	1246'	Drlg. 1246' (0' in 8 hrs ) Lime. Drilled 5' to 1075'
6/16/78	1246'	Drlg. 1246' (0'in 8 hrs) Lime. Drilled 6' to 1081'. (" bailer will go to 1093'.