

OF COPIES RECEIVED	
DISTRIBUTION	
ANTA FE	<input checked="" type="checkbox"/>
ILE	<input checked="" type="checkbox"/>
.S.G.S.	<input checked="" type="checkbox"/>
AND OFFICE	<input checked="" type="checkbox"/>
PERATOR	<input checked="" type="checkbox"/>

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIV

SEP -7 '89

G. C. D.
ARTESIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-85

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. OG - 4659	
7. Unit Agreement Name East Red Lake Unit	
8. Farm or Lease Name Tract 2	
9. Well No. 1	
10. Field and Pool, or Wildcat East Red Lake Queen GB	
12. County Eddy	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☐ OTHER- Injection well

Name of Operator
Kincaid & Watson Drilling Company

Address of Operator
P.O. Box 498, Artesia, New Mexico 88211-0498

Location of Well
UNIT LETTER P 330 FEET FROM THE South LINE AND 330 FEET FROM THE East LINE, SECTION 35 TOWNSHIP 16S RANGE 28E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
3596 GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> JLL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 103.

We propose to plug this well as follows:

35 sacks at 1549' on top of bridge plug. 100'.
 Cut 5 1/2" casing at free point and pull.
 Set plug 50' in and 50' out of stub.
 100' plug 50' below base of surface pipe and 50' above surface pipe.
 Tag plugs.
 5 sacks at surface. Set dry hole marker and clean up location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Harvey King TITLE Secretary-Treasurer DATE 9-7-89
 ORIGINAL SIGNED BY MIKE WILLIAMS DATE SEP 8 1989
 CONDITIONS OF APPROVAL SUPERVISOR, DISTRICT II

Notify N.M.O.C.C. in sufficient time to witness

Plugging