

YATES PETROLEUM CORPORATION  
Martin ARH #1  
Section 27-T17S-R26E  
Eddy County, New Mexico

APPLICATION TO PLUG BACK (CONTINUED):

Add perforations in Strawn as follows:

1. Set RBP at 8250' and test.
2. Perforate 8202-8210' (Strawn), acidize and frac as necessary.
3. Swab test.

Add perforations in Canyon as follows:

1. Set RBP at 8000' and test.
2. Perforate 7900-7905' (Canyon), acidize and frac as necessary.
3. Swab test.
4. Set RBP at 7250' and test.
5. Perforate 7098-7207' (Canyon/Cisco), acidize and frac as necessary.
6. Swab test.

Depending on productivity of each zone, plans may be made to pull RBP and place all zones into production.



Rusty Klein  
Operations Technician  
March 4, 1998