

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-015-04424

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

B-4108

7. Lease Name or Unit Agreement Name

State BX

8. Well No.

5

9. Pool name or Wildcat

Loco Hills Queen G-SA

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OE.
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

YATES PETROLEUM CORPORATION

3. Address of Operator

105 South Fourth Street - Artesia, NM 88210

4. Well Location

Unit Letter M : 330 Feet From The South Line and 990 Feet From The West Line

Section 32

Township 17S

Range 30E

NMPM

Eddy

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: Temporary Abandon ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to temporary abandon as follows:

1. POOH with tubing and packer.
2. RIH w/bit and scraper on tubing and clean out to 2760'. POOH.
3. GIH w/7" CIBP and set at 2715'. Dump 35' of cement on top of CIBP.
4. Pressure test casing to 500 psi. NOTE: Have OCD officials witness the test.
5. If casing tests okay, install pressure gauge and move out pulling unit.

NOTE: If casing does not test, will follow procedure to plug and abandon as follows:

1. GIH w/perforating gun and perforate 4 holes at 2340'. POOH. GIH w/cement retainer on 2-3/8" tubing and set cement retainer at 2290'. Squeeze Queen with 50 sacks Class "C" 2% CaCl2. Dump 35' of cement on top of cement retainer.

CONTINUED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Production Clerk

DATE 6-28-94

TYPE OR PRINT NAME

Rusty Klein

505-748-1471
TELEPHONE NO.

(This space for State Use)

SUPERVISOR, DISTRICT II

SUPERVISOR, DISTRICT II

JUL 11 1994

TITLE

DATE

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department.

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-015-04424

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

B-4108

7. Lease Name or Unit Agreement Name

State BX

8. Well No.

5

9. Pool name or Wildcat

Loco Hills Queen G-SA

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" RECEIVED
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

YATES PETROLEUM CORPORATION

3. Address of Operator

105 South Fourth Street - Artesia, NM 88210

4. Well Location

Unit Letter M : 330 Feet From The South Line and 990 Feet From The West Line

Section 32

Township 17S

Range 30E

NMPM

Eddy

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

TEMPORARILY ABANDON ☐

PULL OR ALTER CASING ☐

OTHER: Temporary Abandon ☒

PLUG AND ABANDON ☒

CHANGE PLANS ☐

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

CONTINUED FROM PREVIOUS PAGE:

- GIH w/perforating gun and perforate 4 holes at 1157'. POOH. GIH w/cement retainer on 2-3/8" tubing and set cement retainer at 1107'. Squeeze Base of Salt with 50 sacks Class "C" 2% CaCl₂. Dump 35' of cement on top of cement retainer. WOC.
- Perforate 4 holes at 445' GIH w/cement retainer on 2-3/8" tubing and set cement retainer at 395'. Squeeze top of Salt with 50 sacks Class "C" 2% CaCl₂. Dump 35' of cement on top of cement retainer. POOH.
- RIH w/perforating gun and perforate 4 holes at 250'. Pump 50 sacks Class "C" out of holes and leave 100' of cement in casing. WOC.
- RIH and tag plug at 150' or higher.
- 15 sack cement plug at surface (at least 50').
- Install regulation abandonment marker.

NOTE: Heavy mud will be placed between all plugs.

NOTIFY OCD (748-1283) AND BLM (887-6544) 24 HOURS PRIOR TO COMMENCING OPERATIONS.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Production Clerk

DATE 6-28-94

TYPE OR PRINT NAME

Rusty Klein

505-748-1471
TELEPHONE NO.

(This space for State Use)

TITLE

DATE