Form 3160-5 (November 1983)

(This space for Federal or State office use)

AL, IF ANY:

APPROVED BY

CONDITIONS OF API

UNITED STATES THE INTERIOR

RC. WELL FIELD OFFICE SUBMIT IN TRIPLICATE * (Other Instructions

Car Vureau No. 1004-0135 Expires August 31, 1985

DEPARTMENT (Formerly 9-331) reverse side) **BUREAU OF LAND MANAGEMENT** 5. LEASE DESIGNATION AND SERIAL NO. LC-029418-A SUNDRY NOTICES AND REPORTS ON WELLS 6. IF INDIAN, ALLOTTEE OR TRIBE NAME (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT - " for such proposals.) 1. 7. UNIT AGREEMENT NAME OIL GAS OTHER Skelly Unit WELL WELL wiw 2. NAME OF OPERATOR 8. WELL NO. The Wiser Oil Company 49 ADDRESS OF OPERATOR 9. API Well No. P.O. Box 2568 Hobbs, New Mexico 88240 (505) 392-9797 30-015-05359 LOCATION OF WELL (Report location clearly and in accordance with any State requirements. 10. FIELD AND POOL, OR WILDCAT See also space 17 below.) Grayburg Jackson 7-Rivers-QN-GB-SA At surface 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 1980' FNL & 1980' FEL Unit G Sec. 23-T17S-R31E 14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 12. COUNTY OR PARISH 13. STATE 3879' DF **Eddy County NM** 16. Check Appropriate Box to indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: TEST WATER SHUT OFF PULL OR ALTER CASING WATER SHUT-OFF REPAIRING WELL FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT ALTERING CASING SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING ABANDONMENT * REPAIR WELL **CHANGE PLANS** (Other) (Note: Report results of multiple completion on Well (Other) Completion or Recompletion Report and Log form.) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work. Wiser requests approval to plug and abandon the well by the procedure listed below. Williams. Surface Casing: 8-5/8" set @ 694' Production Casing: 7" @ 3255 Liner: 4-1/2" @ 3693 10 ণ Perforations: 3320'-3596' 1. TOH w/tbg. TIH w/CIBP & set @ 3300'. Cap w/50' cement. 2. Tag cement & circulate abandomment mud.
1700, PERF & SQUEEZE.
3. TOH to 1600 & set 100' cement plug (1500-160) "csg. @ 700-% circulate cement to surface. Leave 100' cement plug @ 600'-700'. APPROVAL SUBJECT TO 4. Tag cement plug @ 1500'. Perforate 4-1/2' 5. Spot 50' cement plug to surface. GENERAL REQUIREMENTS AND 6. Install dry hole marker. SPECIAL STIPULATIONS AT JACHED Clean location. commendation of 18. I hereby certify that the foregoing is true and correct SIGNED TITLE Superintendent October 19, 2001

*See Instruction On Reverse Side

BETTO ELIM ENGINEER

DATE

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

valodous