

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-03384
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-6631-24
7. Lease Name or Unit Agreement Name West Loco Hills Unit #37-2
8. Well No. 37-2
9. Pool name or Wildcat Loco Hills - Q - G - SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Injection Well
2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South Fourth Street - Artesia, NM 88210
4. Well Location Unit Letter A : 330' Feet From The FNL Line and 990' Feet From The FEL Line Section 11 Township 18S Range 29E NMPM EDDY County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.

RECEIVED

OCT 18 1995

OIL CON. DIV.  
DIST. 2

Propose to P&A. NOTE: Notify BLM & NMOC D prior to plugging.

1. MIRUPU. POOH w/tubing and packer.
2. RIH w/bit & scraper, clean out to 2590'. POOH.
3. GIH w/CIBP & set at 2590'. Cement 125' on top of plug.
4. GIH & perf 4 holes at 2180'. POOH. GIH w/cement retainer and set at 2130'. Squeeze Base of Salt w/50 sxs Class "C", w/2%CaCl2. Cement 35' on CR. POOH.
5. GIH & perf 4 holes at 960'. POOH. GIH w/cement retainer and set at 910'. Squeeze Base of Salt w/50 sxs Class "C", w/2%CaCl2. Cement 35' on CR. POOH.
6. Cut and pull 4 1/2" casing at 462'. 6. Perf 579X50 w/35 SXS LEAVE 100' CMT ARCUB 5-75' AND TAG
7. GIH w/cement retainer and set at 412'. Squeeze Top of Salt w/50sxs Class "C", w/2%CaCl2. Cement 35' on CR. POOH.
8. GIH & set Cement plug f/300'-150'.
9. RIH & tag Plug at 150' or higher.
10. Cement Abandonment marker w/15 sx plug (at least 50').

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Pamela Evans TITLE Production Clerk DATE 10-17-95

TYPE OR PRINT NAME Rusty Klein / Pamela Evans

505-748-1471  
TELEPHONE NO.

(This space for State Use) ORIGINAL SIGNED BY TIM W. GUM  
DISTRICT II SUPERVISOR

OCT 20 1995

APPROVED BY

TITLE

DATE