

*C/SF  
gr*

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

**OIL CONSERVATION DIVISION**

2040 Pacheco St.  
Santa Fe, NM 87505

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-015-10540
Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
State Oil & Gas Lease No.

<p align="center"><b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>Lease Name or Unit Agreement Name State 647 AC 731</p>
Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER WIW <input type="checkbox"/>		
Name of Operator Melrose Operating Co.	Well No. 205	
Address of Operator PO Box 5061, Midland, TX 79704	Pool name or Wildcat Artesia QN-GB-SA	
Well Location Unit Letter <u>A</u> <u>330</u> Feet From The <u>North</u> Line and <u>990</u> Feet From The <u>East</u> Line Section <u>33</u> Township <u>18S</u> Range <u>28E</u> NMPM <u>Eddy</u> County		
Elevation (Show whether DF, RKB, RT, GR, etc.)		

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ANBANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/27/00 -  
Notify OCD. Move equip to loc. MI & RU. ND wellhead. NU BOP. Unset pkr. POH. RIH & set CIBP @ 1950'. RIH w/tbg. Load hole w/10# mud. Spot 25 sx @ 1950'. POH. Take stretch on csg. Shows loose @ 900'. Call OCD. RIH & spot 15 sx @ 1600'. POH. Close in well.

6/28/00 -  
RIH & cut csg @ 880'. LD 26 jts. RIH w/tbg to 930'. Spot 50 sx. POH. WOC for 4 hrs per OCD. Tag @ 596'. Spot 35 sx @ 596'. POH. WOC. Tag @ 465'. POH & spot 10 sx @ 30' to surf. RD. Cut off wellhead. Level pit & cellar.

Install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bonnie Atwater TITLE Regulatory Tech. DATE 07-20-00

TYPE OR PRINT NAME Bonnie Atwater TELEPHONE NO 915/685-1761

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep I DATE 7-26-00

CONDITIONS OF APPROVAL, IF ANY: