

NEW MEXICO OIL CONSERVATION COMMISSION RECEIVED

OCT 17 1978

O. C. C.
 ARTESIA, OFFICE

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-4477
7. Unit Agreement Name
8. Farm or Lease Name Sulphate Cousin
9. Well No. 1
10. Field and Pool, or Wildcat Wildcat
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- 2. Name of Operator Corinne Grace ✓ 3. Address of Operator P. O. Box 1418, Carlsbad, New Mexico 88220 4. Location of Well UNIT LETTER <u>E</u> 1980 FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>15</u> TOWNSHIP <u>25S</u> RANGE <u>27E</u> NMPM.

15. Elevation (Show whether DF, RT, GR, etc.) 3154.9

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

T.D. 690'
 16" casing set to a depth of 350' but not cement in. Will try to pull but if unable to
 12 1/2 hole out of casing will plug as follows:

Plug 325-425 with 100 sx
 0- 30 with 20 sx
 Go down backside of 16" as far as can and put 100 sx cement
 tag plug @ 325' make sure it stays
 Set dry hole marker

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jeannette Jones Wildberger TITLE Agent DATE 10/16/78

APPROVED BY W. A. Gressett TITLE SUPERVISOR, DISTRICT II DATE OCT 18 1978

CONDITIONS OF APPROVAL, IF ANY:
Load hole w/ mud Notify N.M.O.C.C. in sufficient time to witness
J. Messinger