	,			· · · · · · · · · · · ·	Crus	. Division		10
				811 S. 1st	5	u đội sa		C(S)
Form 3160-5		UNITED STATES	S	811 0. 151 M	M 88	1 210-2834 FOR D <u>Febr</u>	MAPPROVED	01
(June 1990)		MENT OF THE I	NTERIOR	RECEI		E	BLM - CRA	
	BUREAU	OF LAND MANA	AGEMENT		ACL	J Febr	uary 08, 1996	
	SUNDRY NOTIO	CES AND REPO	ام RTS ON W	97 JUN - 9	4 9	15 Lease Designa	ation and Serial N	0.
Do not use this fo	orm for proposals to dri	Il or to deepen or r	eentry to a d	ifferent reserve	oir	6 If Indian Allote		·
L			ch proposal	CAU OF LA	ND M	GMT.		
1. Type of Well	SUBMIT I	N TRIPLICATE				7. If Unit or CA, A	greement Desig	nation
X Oil Well	Gas Well	[] <b>(</b> ]	her	و هرچه در ا این سره	<i>:</i>	Delres Leite Linit		
2. Name of Operator				······		Poker Lake Unit 8. Well Name and		
Bass Enterp	rises Production Company					Poker Lake Unit #		
3. Address and Telephone						9. API Well No.		
P. O. Box 27						30-015-27920		
	as 79702-2760		15) 683-2277			10. Field and Poo	I, or Exploratory	Area
4. Location of Well (Footag	e, Sec., T., R., M., or Surve	y Description)				Poker Lake (Delat 11. County or Par	ware)	
1980' FWL 8	1980' FSL, Section 25, T2	4S-R30E				11. County or Par	isn, State	
						Eddy County, Nev		
12. CHECK A			NATURE	OF NOTICE,	REPC	ORT, OR OTHE	R DATA	
TYPE OF SUBMIS	SSION			TYPE OF ACT				
Notice of Inte	nt T	Abandonment	AUGEPTED	R0077 5 7	0	Change of Plans		
		Recompletion	1	· · · · · · · · · · · · · · · · · · ·		New Construction		
X Subsequent	Report	Plugging Back		3 0 1037		Non-Routine Frac		
		Casing Repair						
			3			Water Shut-Off		
Final Abando	nment Notice	Altering Casing	1 1 1 1	acr		Water Shut-Off Conversion to Inje	ction	
Final Abando	nment Notice	Altering Casing	ud, Casing, Ce	acr			ction	
Final Abando	nment Notice	Altering Casing	ud, Casing, Ce	acr		Conversion to Inje		on Well
		Altering Casing X Other Spu		ort, TD		Conversion to Inje Dispose Water (Note: Report results of Completion or Recomp	f multiple completion o letion Report and Log	form.)
13. Describe Proposed or Comple give subsurface locations and Spud @ 9:00 Drilled 14–3/4 Ran 18 joints	ted Operations (Clearly state all per measured and true vertical depths a.m. 4/24/97. " hole to 804' 4/26/97 11-3/4" 42#, WC-40 casing	Altering Casing X Other Sput tinent details, and give perti for all markers and zones p set at 804'. Cemente	inent dates, includi ertinent to this wor	ment, TD		Conversion to Inje Dispose Water (Note: Report results of Completion or Recomp	f multiple completion of iletion Report and Log is directionally drilled,	form.)
13. Describe Proposed or Comple give subsurface locations and Spud @ 9:00 Drilled 14–3/4 Ran 18 joints Circulated 11	ted Operations (Clearly state all per measured and true vertical depths a.m. 4/24/97. " hole to 804' 4/26/97	Altering Casing X Other Sput tinent details, and give perti for all markers and zones p set at 804'. Cemente 1/2 hours.	inent dates, includi ertinent to this wor	ment, TD		Conversion to Inje Dispose Water (Note: Report results of Completion or Recomp	f multiple completion of iletion Report and Log is directionally drilled,	form.)
13. Describe Proposed or Comple give subsurface locations and Spud @ 9:00 Drilled 14–3/4 Ran 18 joints Circulated 11 Drill cement a	ted Operations (Clearly state all per measured and true vertical depths a.m. 4/24/97. " hole to 804' 4/26/97 11-3/4" 42#, WC-40 casing 6 sx to surface, W.O.C. 14- ind test casing to 1000 psi, i	Altering Casing X Other Sput tinent details, and give perti for all markers and zones p set at 804'. Cemente 1/2 hours.	inent dates, includi ertinent to this wor	ment, TD		Conversion to Inje Dispose Water (Note: Report results of Completion or Recomp	f multiple completion of iletion Report and Log is directionally drilled,	form.)
13. Describe Proposed or Comple give subsurface locations and Spud @ 9:00 Drilled 14–3/4 Ran 18 joints Circulated 11 Drill cement a Drilled 11" ho	ted Operations (Clearly state all per measured and true vertical depths a.m. 4/24/97. " hole to 804' 4/26/97 11-3/4" 42#, WC-40 casing 6 sx to surface, W.O.C. 14- ind test casing to 1000 psi, of le to 4161' 5/4/97	Altering Casing X Other Sput tinent details, and give perti for all markers and zones p set at 804'. Cemente 1/2 hours. DK.	inent dates, includi wertinent to this wor ed with 290 sx t	ment, TD ng estimated date of tk.)*	litives. 7	Conversion to Inje Dispose Water (Note: Report results of Completion or Recomp py proposed work. If well Fail with 240 sx Class	f multiple completion of iletion Report and Log is directionally drilled, ss with additives.	form.)
13. Describe Proposed or Comple give subsurface locations and Drilled 14-3/4 Ran 18 joints Circulated 11 Drill cement a Drilled 11" ho Ran 25 joints Cemented wit	ted Operations (Clearly state all per measured and true vertical depths " hole to 804' 4/26/97 11-3/4" 42#, WC-40 casing 6 sx to surface, W.O.C. 14- ind test casing to 1000 psi, i le to 4161' 5/4/97 8-5/8" 32# WC-50 LT&C ca h 931 sx 35/65 Poz C with a 0000 psi high, 200 psi low, C	Altering Casing X Other Spir tinent details, and give perti- for all markers and zones p 1 set at 804'. Cementer 1/2 hours. DK. asing and 71 joints 5-1 additives, Tail with 150	inent dates, includii vertinent to this wor ed with 290 sx ( 1/2" 28# WC-50 0 sx Class C No	ment, TD rg estimated date of tk.)* Class C with add 0 LT&C casing. eat. Circulate 12	Total of 0 sx to s	Conversion to Inje Dispose Water (Note: Report results of Completion or Recomp py proposed work. If well Fail with 240 sx Class 96 joints set at 416	f multiple completion of iletion Report and Log is directionally drilled, ss with additives.	form.)
13. Describe Proposed or Comple give subsurface locations and Spud @ 9:00 Drilled 14–3/4 Ran 18 joints Circulated 11 Drill cement a Drilled 11" ho Ran 25 joints Cemented wit Test BOPE, 3 Drilling 7-7/8" Ran 144 joints Cement in two	ted Operations (Clearly state all per measured and true vertical depths a.m. 4/24/97. " hole to 804' 4/26/97 11-3/4" 42#, WC-40 casing 6 sx to surface, W.O.C. 14- ind test casing to 1000 psi, if le to 4161' 5/4/97 8-5/8" 32# WC-50 LT&C ca h 931 sx 35/65 Poz C with a 000 psi high, 200 psi low, C hole 5/5/97. hole to 8138' 5/13/97. s 5-/12" 15.5# K-55 LT&C c o stages. Stage 1) 165 sx C	Altering Casing X Other Sput tinent details, and give perti- for all markers and zones p 1 set at 804'. Cementer 1/2 hours. OK. asing and 71 joints 5-1 additives, Tail with 150 DK. Drill cement and f asing (0-6481') and 45 lass H with additives,	inent dates, includi ertinent to this wor ed with 290 sx f 1/2" 28# WC-5 0 sx Class C No formation test c 5 joints 17# K-5 circ 35 sx cerr	ng estimated date of k)* Class C with add D LT&C casing. Eat. Circulate 12 asing to 1000 ps	Total of 0 sx to s i OK. (6481-8	Conversion to Inje Dispose Water (Note: Report results of Completion or Recomp py proposed work. If well Fail with 240 sx Class 96 joints set at 416 surface. W.O.C. 20-	f multiple completion of iletion Report and Log is directionally drilled, as with additives. 1'. -1/2 hours.	form.)
13. Describe Proposed or Comple give subsurface locations and Spud @ 9:00 Drilled 14-3/4 Ran 18 joints Circulated 11 Drill cement a Drilled 11" ho Ran 25 joints Cemented wit Test BOPE, 3 Drilling 7-7/8" Ran 144 joints Cement in two W.O.C. 4 hou	ted Operations (Clearly state all per measured and true vertical depths a.m. 4/24/97. " hole to 804' 4/26/97 11-3/4" 42#, WC-40 casing 6 sx to surface, W.O.C. 14- ind test casing to 1000 psi, in le to 4161' 5/4/97 8-5/8" 32# WC-50 LT&C ca h 931 sx 35/65 Poz C with a W000 psi high, 200 psi low, C hole 5/5/97. hole to 8138' 5/13/97. s 5-/12" 15.5# K-55 LT&C c o stages. Stage 1) 165 sx C ars. Plug down @ 3:59 a.m	Altering Casing X Other Sput tinent details, and give perti- for all markers and zones p 1 set at 804'. Cementer 1/2 hours. OK. asing and 71 joints 5-1 additives, Tail with 150 DK. Drill cement and f asing (0-6481') and 45 lass H with additives,	inent dates, includi ertinent to this wor ed with 290 sx f 1/2" 28# WC-5 0 sx Class C No formation test c 5 joints 17# K-5 circ 35 sx cerr	ng estimated date of k)* Class C with add D LT&C casing. Eat. Circulate 12 asing to 1000 ps	Total of 0 sx to s i OK. (6481-8	Conversion to Inje Dispose Water (Note: Report results of Completion or Recomp py proposed work. If well Fail with 240 sx Class 96 joints set at 416 surface. W.O.C. 20-	f multiple completion of letion Report and Log is directionally drilled, as with additives. 1'. -1/2 hours. 500' & 7000'. itives. Lost return	form.)
<ul> <li>13. Describe Proposed or Complegive subsurface locations and Spud @ 9:00 Drilled 14-3/4 Ran 18 joints Circulated 111 Drill cement a Drilled 11" ho Ran 25 joints Cemented wit Test BOPE, 3 Drilling 7-7/8" Prilled 7-7/8" Ran 144 joints Cement in two W.O.C. 4 hou Prep for comp</li> </ul>	ted Operations (Clearly state all per measured and true vertical depths a.m. 4/24/97. " hole to 804' 4/26/97 11-3/4" 42#, WC-40 casing 6 sx to surface, W.O.C. 14- ind test casing to 1000 psi, in le to 4161' 5/4/97 8-5/8" 32# WC-50 LT&C ca h 931 sx 35/65 Poz C with a 1000 psi high, 200 psi low, C hole 5/5/97. hole to 8138' 5/13/97. a 5-/12" 15.5# K-55 LT&C c o stages. Stage 1) 165 sx C urs. Plug down @ 3:59 a.m.	Altering Casing X Other Sput tinent details, and give perti- for all markers and zones p 1 set at 804'. Cementer 1/2 hours. OK. asing and 71 joints 5-1 additives, Tail with 150 DK. Drill cement and f asing (0-6481') and 45 lass H with additives,	inent dates, includi ertinent to this wor ed with 290 sx f 1/2" 28# WC-5 0 sx Class C No formation test c 5 joints 17# K-5 circ 35 sx cerr	ng estimated date of k)* Class C with add D LT&C casing. Eat. Circulate 12 asing to 1000 ps	Total of 0 sx to s i OK. (6481-8	Conversion to Inje Dispose Water (Note: Report results of Completion or Recomp py proposed work. If well Fail with 240 sx Class 96 joints set at 416 surface. W.O.C. 20-	f multiple completion of iletion Report and Log is directionally drilled, as with additives. 1'. -1/2 hours.	<u>form.)</u>
<ul> <li>13. Describe Proposed or Complegive subsurface locations and Spud @ 9:00 Drilled 14-3/4 Ran 18 joints Circulated 111 Drill cement a Drilled 11" ho Ran 25 joints Cemented wit Test BOPE, 3 Drilling 7-7/8" Drilled 7-7/8" Ran 144 joints Cement in two W.O.C. 4 ho Prep for comp</li> <li>4. I hereby certify that the formation of the subsurface location of the subsurface location of the subsurface locations and the subsurface locations are subsurface. Subsurface locations are subsurface locations and the subsurface locations are subsurface. Subsurface locations are subsurface locations and the subsurface locations are subsurface. Subsu</li></ul>	ted Operations (Clearly state all per measured and true vertical depths a.m. 4/24/97. " hole to 804' 4/26/97 11-3/4" 42#, WC-40 casing 6 sx to surface, W.O.C. 14- ind test casing to 1000 psi, 4 le to 4161' 5/4/97 8-5/8" 32# WC-50 LT&C ca h 931 sx 35/65 Poz C with a W000 psi high, 200 psi low, C hole 5/5/97. hole to 8138' 5/13/97. s 5-/12" 15.5# K-55 LT&C c o stages. Stage 1) 165 sx C urs. Plug down @ 3:59 a.m. letion.	Altering Casing X Other Sput tinent details, and give perti- for all markers and zones p 1 set at 804'. Cementer 1/2 hours. OK. asing and 71 joints 5-1 additives, Tail with 150 DK. Drill cement and f asing (0-6481') and 45 lass H with additives,	inent dates, includi ertinent to this wor ed with 290 sx f 1/2" 28# WC-5 0 sx Class C No formation test c 5 joints 17# K-5 circ 35 sx cerr	ng estimated date of k)* Class C with add D LT&C casing. Eat. Circulate 12 asing to 1000 ps	Total of 0 sx to s i OK. (6481-8	Conversion to Inje Dispose Water (Note: Report results of Completion or Recomp py proposed work. If well Fail with 240 sx Class 96 joints set at 416 surface. W.O.C. 20-	f multiple completion of letion Report and Log is directionally drilled, as with additives. 1'. -1/2 hours. 500' & 7000'. itives. Lost return	<u>form.)</u>
<ul> <li>13. Describe Proposed or Complegive subsurface locations and Spud @ 9:00 Drilled 14-3/4 Ran 18 joints Circulated 11 Drill cement a Drilled 11" ho Ran 25 joints Cemented wit Test BOPE, 3 Drilling 7-7/8" Drilled 7-7/8" Ran 144 joints Cement in two W.O.C. 4 ho Prep for comp</li> <li>4. I hereby certify that the formation of the subsurface location of the subsurface locations and the subsurface locations and the subsurface location of the subsu</li></ul>	ted Operations (Clearly state all per measured and true vertical depths a.m. 4/24/97. " hole to 804' 4/26/97 11-3/4" 42#, WC-40 casing 6 sx to surface, W.O.C. 14- ind test casing to 1000 psi, in le to 4161' 5/4/97 8-5/8" 32# WC-50 LT&C ca h 931 sx 35/65 Poz C with a 1000 psi high, 200 psi low, C hole 5/5/97. hole to 8138' 5/13/97. a 5-/12" 15.5# K-55 LT&C c o stages. Stage 1) 165 sx C urs. Plug down @ 3:59 a.m.	Altering Casing X Other Sput tinent details, and give perti- for all markers and zones p 1 set at 804'. Cementer 1/2 hours. OK. asing and 71 joints 5-1 additives, Tail with 150 DK. Drill cement and f asing (0-6481') and 45 lass H with additives,	inent dates, includi ertinent to this wor ed with 290 sx f 1/2" 28# WC-5 0 sx Class C No formation test c 5 joints 17# K-5 circ 35 sx cerr	ng estimated date of k)* Class C with add D LT&C casing. Eat. Circulate 12 asing to 1000 ps	Total of 0 sx to s i OK. (6481-8 2) 255 s	Conversion to Inje Dispose Water (Note: Report results of Completion or Recomp py proposed work. If well Fail with 240 sx Class 96 joints set at 416 surface. W.O.C. 20-	f multiple completion of letion Report and Log is directionally drilled, as with additives. 1'. -1/2 hours. 500' & 7000'. itives. Lost return	<u>form.)</u>
<ul> <li>13. Describe Proposed or Complegive subsurface locations and Spud @ 9:00 Drilled 14-3/4 Ran 18 joints Circulated 11<sup>11</sup> Drill cement a Drilled 11<sup>11</sup> ho Ran 25 joints Cemented wit Test BOPE, 3 Drilling 7-7/8" Drilled 7-7/8" Ran 144 joints Cement in two W.O.C. 4 hot Prep for comp</li> <li>4. I hereby certify that the for Signed <u>Jamma</u></li> </ul>	ted Operations (Clearly state all per measured and true vertical depths a.m. 4/24/97. "hole to 804' 4/26/97 11-3/4" 42#, WC-40 casing 6 sx to surface, W.O.C. 14- ind test casing to 1000 psi, if le to 4161' 5/4/97 8-5/8" 32# WC-50 LT&C ca h 931 sx 35/65 Poz C with a 1000 psi high, 200 psi low, C hole 5/5/97. hole to 8138' 5/13/97. a 5-/12" 15.5# K-55 LT&C c o stages. Stage 1) 165 sx C urs. Plug down @ 3:59 a.m. letion. Dregoing is true and correct L. WULL	Altering Casing X Other Spir tinent details, and give perti- for all markers and zones p set at 804'. Cemente 1/2 hours. OK. asing and 71 joints 5-1 additives, Tail with 150 OK. Drill cement and f asing (0-6481') and 44 lass H with additives, . 5/12/97. Rig release	inent dates, includi wertinent to this wor ed with 290 sx f 1/2" 28# WC-56 0 sx Class C No formation test c 5 joints 17# K-5 circ 35 sx cerr ed @ 9:00 p.m	DLT&C casing. eat. Circulate 12 asing to 1000 ps 55 LT&C casing nent to pit. Stage on 5/12/97.	Total of 0 sx to s i OK. (6481-8 2) 255 s	Conversion to Inje Dispose Water (Note: Report results of Completion or Recomp by proposed work. If well Fail with 240 sx Class 96 joints set at 416 surface. W.O.C. 20- 138'). DV tool @ 55 sx Class H with add <u>attigued</u>	f multiple completion of letion Report and Log is directionally drilled, as with additives. 1'. 1/2 hours. 500' & 7000'. litives. Lost return P = 466	form.)
<ul> <li>13. Describe Proposed or Comple give subsurface locations and Drilled 14-3/4 Ran 18 joints Circulated 11: Drill cement a Drilled 11" ho Ran 25 joints Cemented wit Test BOPE, 3 Drilling 7-7/8" Drilled 7-7/8" Ran 144 joints Cement in two W.O.C. 4 hou Prep for comp</li> <li>4. I hereby certify that the for Signed <u>Jamm</u></li> </ul>	ted Operations (Clearly state all per measured and true vertical depths a.m. 4/24/97. "hole to 804' 4/26/97 11-3/4" 42#, WC-40 casing 6 sx to surface, W.O.C. 14- ind test casing to 1000 psi, in le to 4161' 5/4/97 8-5/8" 32# WC-50 LT&C ca h 931 sx 35/65 Poz C with a k000 psi high, 200 psi low, C hole 5/5/97. hole to 8138' 5/13/97. a 5-/12" 15.5# K-55 LT&C c o stages. Stage 1) 165 sx C urs. Plug down @ 3:59 a.m. letion. pregoing is true and correct U.U.U.U.	Altering Casing X Other Spir tinent details, and give perti- for all markers and zones p set at 804'. Cemente 1/2 hours. OK. asing and 71 joints 5-1 additives, Tail with 150 OK. Drill cement and f asing (0-6481') and 44 lass H with additives, . 5/12/97. Rig release	inent dates, includi wertinent to this wor ed with 290 sx f 1/2" 28# WC-56 0 sx Class C No formation test c 5 joints 17# K-5 circ 35 sx cerr ed @ 9:00 p.m	DLT&C casing. eat. Circulate 12 asing to 1000 ps 55 LT&C casing nent to pit. Stage on 5/12/97.	Total of 0 sx to s i OK. (6481-8 2) 255 s	Conversion to Inje Dispose Water (Note: Report results of Completion or Recomp by proposed work. If well Fail with 240 sx Class 96 joints set at 416 surface. W.O.C. 20- 138'). DV tool @ 55 sx Class H with add <u>attigued</u>	f multiple completion of letion Report and Log is directionally drilled, as with additives. 1'. 1/2 hours. 500' & 7000'. litives. Lost return P = 466	form.)
<ul> <li>13. Describe Proposed or Comple give subsurface locations and Spud @ 9:00 Drilled 14-3/4 Ran 18 joints Circulated 11<sup>11</sup> Drill cement a Drilled 11<sup>11</sup> ho Ran 25 joints Cemented wit Test BOPE, 3 Drilling 7-7/8" Drilled 7-7/8" Ran 144 joints Cement in two W.O.C. 4 hou Prep for comp</li> <li>4. I hereby certify that the for Signed <u>Jamma</u></li> </ul>	ted Operations (Clearly state all per measured and true vertical depths a.m. 4/24/97. "hole to 804' 4/26/97 11-3/4" 42#, WC-40 casing 6 sx to surface, W.O.C. 14- ind test casing to 1000 psi, in le to 4161' 5/4/97 8-5/8" 32# WC-50 LT&C ca h 931 sx 35/65 Poz C with a k000 psi high, 200 psi low, C hole 5/5/97. hole to 8138' 5/13/97. a 5-/12" 15.5# K-55 LT&C c o stages. Stage 1) 165 sx C urs. Plug down @ 3:59 a.m. letion. pregoing is true and correct U.U.U.U.	Altering Casing X Other Spir tinent details, and give perti- for all markers and zones p set at 804'. Cemente 1/2 hours. OK. asing and 71 joints 5-1 additives, Tail with 150 OK. Drill cement and f asing (0-6481') and 44 lass H with additives, . 5/12/97. Rig release	inent dates, includi ertinent to this wor ed with 290 sx f 1/2" 28# WC-50 0 sx Class C No formation test c 5 joints 17# K-5 circ 35 sx cen ed @ 9:00 p.m Title	DLT&C casing. eat. Circulate 12 asing to 1000 ps 55 LT&C casing nent to pit. Stage on 5/12/97.	Total of 0 sx to s i OK. (6481-8 2) 255 s	Conversion to Inje Dispose Water (Note: Report results of Completion or Recomp by proposed work. If well Fail with 240 sx Class 96 joints set at 416 surface. W.O.C. 20- 138'). DV tool @ 55 sx Class H with add <u>Date</u> Date	f multiple completion of letion Report and Log is directionally drilled, as with additives. 1'. 1/2 hours. 500' & 7000'. litives. Lost return P = 466	<u>form.)</u>

÷.

or representaives as to any matter within its jurisdiction.