

July 25, 2014

AMARILLO 921 North Bivins Amarillo, Texas 79107 Phone 806.467.0607 Fax 806.467.0622

Mr. Tomas Oberding NMOCD District I 1625 N. French Dr. Hobbs, NM 88240

ARTESIA

408 West Texas Ave. Artesia, New Mexico 88210 Phone 575 746 8768 Fax 575.748.8905 Subject: **Remediation and Closure Report**

> Devon Energy Thistle Unit #17H API#: 30-025-39893

HOBBS

318 East Taylor Street Hobbs, New Mexico 88241 Phone 505.393.4261 Fax 505,393,4658

Dear Dr. Oberding:

Devon Energy had contracted Talon/LPE (Talon) to perform soil assessment and remediation services at the above referenced location. The completed remediation activities and closure request are submitted herein.

MIDLAND

2901 State Highway 349 Midland, Texas 79706 Phone 432,522,2133 Fax 432,522,2180

Incident Date

May 15, 2014

OKLAHOMA CITY 7700 North Hudson Ave Oklahoma City, Oklahoma 73116 Phone 405.486.7030 Fax 806.467.0622

Background Information

The Thistle Unit No. 17H is located approximately fifty (50) miles southeast of Carlsbad in Lea County, New Mexico. The legal location for this site is Section 33, Township 23 South, and Range 33 East. More specifically the latitude and longitude for the release are 32.254365 North and -103.573475 West. A site plan is presented in Appendix I.

SAN ANTONIO 13111 Lookout Way San Antonio, TX 78233 Phone 210.265.8025 Fax 210.568.2191

According to the soil survey provided by the United States Department of Agriculture Natural Resources Conservation Service, the soil in this area is made up of Berino-Cacique association, hummocky. The local surface and shallow geology, Quaternary Age sedimentary deposits, is comprised of sandy eolian deposits derived from sedimentary rock over calcareous sandy alluvium derived from sedimentary rock. Drainage courses in this area are According to the New Mexico State Engineer web site normally dry. indicates the nearest ground water data to be in S28-T23S-R33E. The ground water in Section 3 is reported to be a depth of 400' below ground surface (bgs). See Appendix II for the referenced groundwater data.

ENVIRONMENTAL CONSULTING ENGINEERING DRILLING CONSTRUCTION SPILL MANAGEMENT GENERAL CONTRACTING

The ranking for this site is 0 based on the following:

Depth to ground water >100' Wellhead Protection Area >1000' Distance to surface water body >1000°

Toll Free: 866,742,0742 www.talonlpe.com

Incident Description

The SWD line was hit by road bore crew causing a release of 50 barrels produced water. The line was isolated and repaired. Approximately 95 percent of the release remained in the bell holes and the rest flowed down caliche road. A vac truck was immediately called to the location and recovered 50 barrels.

Remedial Actions Taken

On July 10, 2014 approval of our work plan was granted from Hobbs NMOCD. On July 25, 2014 a composite 20 millimeter liner was installed under the pipeline at a depth of approximately 6-feet deep under the pipeline. The edges of the liner were keyed into a trench excavated 3-feet deep at the boundaries of the bell holes.

New soil was transported to the location from a local borrow pit and placed over the top of the 20 millimeter liner.

Closure

On behalf of Devon Energy, we respectfully request that no further actions be required and that closure with respect to this release be granted.

Should you have any questions or if further information is required, please do not hesitate to contact our office at (575)-746-8768

M. Wilson

Respectfully submitted,


Kimberly M. Wilson

Project Manager

David J. Adkins

District Manager

APPENDIX I SITE MAP





Drawn By: TJS

Devon Energy Corporation Lea County, New Mexico Figure 1 - Site Plan

APPENDIX II GROUNDWATER DATA



New Mexico Office of the State Engineer Water Column/Average Depth to Water

(A CLW##### in the POD suffix indicates the POD has been replaced & no longer serves a water right file.)

(R=POD has been replaced, O=orphaned,

C=the file is closed)

(quarters are 1=NW 2=NE 3=SW 4=SE)

(quarters are smallest to largest)

(NAD83 UTM in meters)

(In feet)

	POD		10									Ships .		
	Sub-	Q	Q	Q								Depth	Depth	Water
POD Number	Code basin County	64	16	4	Sec	Tws	Rng		Х	Υ	Distance	Well	Water	Column
C 02281	LE	3	4	4	28	23S	33E	634	495	3571183* 🌑	1610	545	400	145
C 02279	LE	3	4	3	28	23S	33E	633	691	3571173* 🌑	1800	650	400	250

Average Depth to Water:

400 feet

Minimum Depth: 400 feet

Maximum Depth: 400 feet

Record Count: 2

UTMNAD83 Radius Search (in meters):

Easting (X): 634516

Northing (Y): 3569573

Radius: 2000

FINAL C-141

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

	-, -, -, -, -, -, -, -, -, -, -, -, -, -										
Release Notification and Corrective Action											
	OPERA	TOR	Initia	☐ Initial Report ☐ Final Report							
Name of Company: DEVON ENERGY	Contact MATT STOUDT										
Address: PO BOX 250 ARTESIA, NM 88211	Telephone No. 575- 748-0188										
Facility Name: THISTLE #17H	Facility Type SWD PIPELINE										
Surface Owner: STATE Mineral Owner	API No. 30-025-35228										
LOCATIO											
Unit Letter Section Township Range Feet from the Nort	h/South Line	Feet from the	East/West Line	East/West Line County LEA							
Latitude: 32.2549969 N Longitude: -103.57056776 W											
	Use Volume of Release 50bbls Volume Recovered 50bbls										
Type of Release: PRODUCED WATER Source of Release: SWD LINE		lour of Occurrence		olume Recovered 50bbls							
Source of Release: SWD LINE		11:20 AM		Date and Hour of Discovery 5/15/14 @ 11:20 AM							
Was Immediate Notice Given?			3/13/14 (4)	W 11:20 AW							
Yes ☐ No ☐ Not Required	If YES, To Whom? MATT STOUDT										
By Whom? WATSON CONSTRUCTION	Date and Hour 5/15/14 @ 11:30 AM										
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.										
☐ Yes ☒ No											
If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* The SWD line was hit by road bore crew causing a release Approximately 95 percent of the release remained in the limmediately called to the location and recovered 50 barrel generate a work plan.	bell holes an	d the rest flow	ved down calich	e road. A	vac truck was						
Describe Area Affected and Cleanup Action Taken.* On July 25, 2014 a composite 20 millimeter liner was installed under the pipeline at a depth of approximately 6-feet deep under the pipeline. The edges of the liner were keyed into a trench excavated 3-feet deep at the boundaries of the bell holes. New soil was transported to the location from a local borrow pit and placed over the top of the 20 millimeter liner. No further actions are required. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.											
federal, state, or local laws and/or regulations.	OIL CONSERVATION DIVISION										
Signature: // Note // Note	OIL CONSLICTATION DIVISION										
Printed Name: MATT STOUDT	Approved by Environmental Specialist:										
Title: ASSISTANT FOREMAN	Approval Date: Expiration			Date:							
E-mail Address: Matthew.Stoudt@dvn.com	Conditions of Approval:			Attached							

^{*} Attach Additional Sheets If Necessary