

**District I**

1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company: Chevron USA Inc.	Contact: Edem Sededji	This is initial only; will be waiting for investigation results.
Address: 15 Smith Rd., Midland, TX, 79705	Telephone No. 432-234-4437	
Facility Name: VGWU Satellite 3	Facility Type: Satellite	
Surface Owner: New Mexico	Mineral Owner: New Mexico	API No. 3002531132

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	1	18S	34E	280	North	2080	East	Lea

Closest well: VGWU 114 Latitude 32.7835 Longitude -103.5123

**NATURE OF RELEASE**

Type of Release: Release to land	Volume of Release: 11 bbls of Produced Water	Volume Recovered: 0
Source of Release: Sump pump	Date and Hour of Occurrence: 05/16/2015 09:30 PM	Date and Hour of Discovery: 05/16/2015 09:30 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

**RECEIVED**  
By OCD District 1 at 7:34 am, May 27, 2015

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
Sump pump overran due to substantial rain fall causing 11.31 bbls of produced water spilled to ground.

Describe Area Affected and Cleanup Action Taken.\*  
The area affected was around Vacuum Glorietta West Unit Battery. A vacuum truck was called out and cleaned up the spill. The next step is for backhoe to excavate top layer of soil approximate 12" deep and soil samples will be taken to the laboratory to determine TPH, Benzene and Chlorides contaminants levels. In case any of the contaminants levels are still high, the spill location will be turned over to Chevron management Company (EMC) for further remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Edem Sededji	Approved by Environmental Specialist:	
Title: HE Specialist	Approval Date: 05/27/2015	Expiration Date: 08/27/2015
E-mail Address: etpo@chevron.com	Conditions of Approval: Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation required.	Attached <input type="checkbox"/> 4323 1RP-3648
Date: 05/26/2015 Phone: 432-234-4437		

\* Attach Additional Sheets If Necessary

pKJ1514728011  
nKJ1514727866